

SEP 12 1985

St. Joseph's Hospital
ATTN: Duane O. Ytredal, M.D.
Director, Radiation
Therapy Department
69 West Exchange Street
St. Paul, MN 55102

Gentlemen:

We have reviewed your letter dated August 1, 1985 requesting review of your teletherapy survey report and find that we will need additional information as follows:

Please describe what tests were conducted to verify the operability of the teletherapy source "on-off" indicators, electrical and mechanical, both at the source housing and at the teletherapy machine control panel. You should use a method of cross-checking these indicators, such as using a radiation detection instrument, to ensure that the indicators correspond to the actual condition of the source.

We will continue our review of your application upon receipt of this information. Please reply in duplicate, within 30 days, and refer to Control Number 79586.

Sincerely,

Original Signed By
William J. Adam, Ph.D.
Materials Licensing Section

8511180364 851002
REG3 LIC30
22-01448-03 PDR

RIII
wja
Adam/cm
09/09/85