

DEC 27 1985

Docket No. 50-346

Toledo Edison Company
ATTN: Mr. Joe Williams, Jr.
Vice President
Nuclear
Edison Plaza
300 Madison Avenue
Toledo, OH 43652

Gentlemen:

This refers to the special safety inspection conducted by Mr. T. Ploski and others of this office on December 2-6, 1985, and to the meeting attended by Mr. M. Phillips of this office on December 10, 1985, regarding activities at Edison Plaza and the Davis-Besse Nuclear Power Station, authorized by NRC Operating License No. NPF-3, and to the discussion of our findings with you and members of your staff at the conclusion of the inspection and meeting.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

"Original signed by W.D. Shafer"

W. D. Shafer, Chief
Emergency Preparedness and
Radiological Protection Branch

Enclosure: Inspection Report
No. 50-346/85038(DRSS)

See Attached Distribution

8512310210 851227
PDR ADOCK 05000346
Q PDR

IESS
//

DEC 27 1985

Distribution

cc w/enclosure:

L. Storz, Plant Manager

DCS/RSB (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII

Harold W. Kohn, Ohio EPA

James W. Harris, State of Ohio

Robert H. Quillin, Ohio

Department of Health

D. Matthews, EPB, OIE

W. Weaver, FEMA, RV

RIII

Ploski/jp

12/27/85

RIII

Williamson

RIII

Phillips

12/27/85

RIII

Jackiw

12/27/85

RIII

Shaffer

12-27-85