

SEP 11 1985

License No. 06-13514-01  
Docket No. 030-06891  
Control No. 03572

Becton-Dickinson  
Division of Becton Dickinson & Company  
ATTN: William R. Case  
Sterilization Supervisor  
Route 7 and Grace Way  
North Canaan, Connecticut 06018

Gentlemen:

Please find enclosed the renewal of your NRC Material License.

Please review the enclosed document carefully and be sure that you understand all conditions. If there are any errors or questions, please notify the Region I Material Licensing Section, (215) 337-5239, so that we can provide appropriate corrections and answers.

Please note that Condition 12. of the license requires the physical presence of responsible individuals whenever the irradiator is in operation.

Please be advised that you must conduct your program involving licensed radioactive materials in accordance with the conditions of your NRC license, representations made in your license application, and NRC regulations. In particular, please note the items in the enclosed, "Requirements for Materials Licensees."

Since serious consequences to employees and the public can result from failure to comply with NRC requirements, the NRC expects licensees to pay meticulous attention to detail and to achieve the high standard of compliance which the NRC expects of its licensees.

You will be periodically inspected by NRC. A fee may be charged for inspections in accordance with 10 CFR Part 170. Failure to conduct your program safely and in accordance with NRC regulations, license conditions, and representations made in your license application and supplemental correspondence with NRC will result in prompt and vigorous enforcement action against you. This could include issuance of a notice of violation, or in case of serious violations, an imposition of a civil penalty or an order suspending, modifying or revoking your license as specified in the General Policy and Procedures for NRC Enforcement Actions, 10 CFR Part 2, Appendix C.

OFFICIAL RECORD COPY

ML 06-13514-01/LTR - 0001.0.0  
09/04/85

8511190073 050911  
REG1 LIC30  
06-13514-01 PDR

ML10

We wish you success in operating a safe and effective licensed program.

Sincerely,

Original Signed By:  
Jack Davis

Jack Davis  
Nuclear Materials Safety Section A  
Division of Radiation Safety  
and Safeguards

RI:DRSS  
Davis/mlb  
9/9/85

RI:DRSS  
Kinneman  
9/1/85

OFFICIAL RECORD COPY

ML 06-13514-01/LTR - 0002.0.0  
09/04/85

6/24/85

TELEPHONE OR VERBAL CONVERSATION RECORD

TIME

☐ A.M.  
☐ P.M.

☐ INCOMING CALL

☐ OUTGOING CALL

☐ VISIT

PERSON CALLING

Jah Doe

OFFICE/ADDRESS

NI

PHONE NUMBER

EXTENSION

PERSON CALLED

Bill Case

OFFICE/ADDRESS

B#D

PHONE NUMBER

EXTENSION

203/824-5487

CONVERSATION

SUBJECT

Renewal of irradiation / Deficiency letter dated 6/3/85

SUMMARY

Need a commitment from B#D for  
1) that they are not By Passing  
Fail Safety Systems (even for maintenance purposes)  
2) Using AECL 40 hr training course  
3) Using AECL instructor to provide training  
Will send in organization chart

Discussed the responsible individual will  
have to be physical present whenever  
the irradiation is in question.

ML10

"OFFICIAL RECORD COPY"

REFERRED TO:

ACTION REQUESTED

ACTION TAKEN

☐ ADVISE ME OF  
ACTION TAKEN.

INITIALS

DATE

INITIALS

DATE