



Our Lady of Mercy Hospital

U.S. Highway 30 Dyer, Indiana 46311-1799 (219) 865-2141

June 13, 1985

Medical Licensing
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Good Day,


Please amend our byproduct material license number 13-12914-01 to include:


<u>Nuclide</u>	<u>Form</u>	<u>Mfg/Model #</u>	<u>Amount</u>
125-I	Ion Exchange	AECL C234	200mCi each; 250mCi total
153GD	GD O ₂	Gulf Nuclear #GD-1	1000mCi each; 1300mCi total

For bone mineral imaging and analyses with Lunar SP2 and Lunar DP3.

Our check in the amount of \$120 is appended.

Sincerely,


Leatrice Coleman
Vice President Patient Care Services


S. Lee, M.D.
Chairperson, Radiation Safety Committee

RWD:cw
Encl: Check

8511190269 851001
REG3 LIC30
13-12914-04 PDR

CONTROL NO. 7 9312

JUL 10 1985

Applicant	July 15 1985
Check No.	019081
Amount Fee Category	8120
Type of Fee	7C and
Date Check Rec'd	7/25/85
Received By	

RECEIVED
JUL 25 AM 1:58
U.S. N.R.C.
LIC. FEE MGMT. BRANCH

RECEIVED
JUL 10 1985
REGION III