



**Foerster Testing**  
**423 Red Twig Drive**  
**Brookings, SD 57006**

May 14, 2020

License Number 40-29268-01  
Docket Number 030-37498  
Control Number 592962

Mr Torres,

My current license allows me to have: Cesium 137- 9 millicuries per source.  
45 millicuries total

Americium-241/ 137- 44 millicuries per source.  
Beryllium 220 millicuries total

We are also requesting to increase those for new gauges (8 gauges) to.

Cesium 137- 9 millicuries per source.  
72 millicuries total

Americium-241/ 137- 44 millicuries per source.  
Beryllium 352 millicuries total

Please let me know if you have any questions or need further information.

Thank you,

Cory Foerster  
423 Red Twig Drive  
Brookings, SD 57006

**FOERSTER TESTING**

Cory Foerster



**ACKNOWLEDGEMENT - RECEIPT OF CORRESPONDENCE**

**Name and Address of Applicant and/or Licensee**

Cory Foerster, Radiation Safety Officer  
Foerster Testing, Ltd.  
1511 Doral Drive  
Brookings, SD 57006

**Date**

05/18/2020

**License Number(s)**

40-29268-01

**Mail Control Number(s)**

618920

**Licensing and/or Technical Reviewer or Branch**

E. Gilman

This is to acknowledge receipt of your: ☒ Letter and/or ☐ Application Dated: 05/14/2020

The initial processing, which included an administrative review, has been performed.

☒ Amendment ☐ Termination ☐ New License ☐ Renewal

☐ There were no administrative omissions identified during our initial review.

☐ This is to acknowledge receipt of your application for renewal of the material(s) license identified above. Your application is deemed timely filed, and accordingly, the license will not expire until final action has been taken by this office.

☐ Your application for a new NRC license did not include your taxpayer identification number. Please complete and submit NRC Form 531, Request for Taxpayer Identification Number, located at the following link: <http://www.nrc.gov/reading-rm/doc-collections/forms/nrc531.pdf>  
Follow the instructions on the form for submission.

☐ The following administrative omissions have been identified:

Your application has been assigned the above listed MAIL CONTROL NUMBER. When calling to inquire about this action, please refer to this control number. Your application has been forwarded to a technical reviewer. Please note that the technical review, which is normally completed within 180 days for a renewal application (90 days for all other requests), may identify additional omissions or require additional information. If you have any questions concerning the processing of your application, our contact information is listed below:

**Region IV**  
**U. S. Nuclear Regulatory Commission**  
**DNMS/NMSB - B**  
**1600 E. Lamar Boulevard**  
**Arlington, TX 76011-4511**  
**(817) 200-1103 or (817) 200-1140**

BETWEEN:

Accounts Receivable/Payable  
and  
Regional Licensing Branches

[ FOR ARPB USE ]  
INFORMATION FROM WBL

Program Code: 03121  
Status Code: Pending Amendment  
Fee Category: 3P  
Exp. Date: 07/31/2027  
Fee Comments:  
Decom Fin Assur Req: N

---

## License Fee Worksheet - License Fee Transmittal

---

### A. REGION

#### 1. APPLICATION ATTACHED

Applicant/Licensee: Foerster Testing, Ltd.  
Received Date: 05/15/2020  
Docket Number: 3037498  
Mail Control Number: 618920  
License Number: 40-29268-01  
Action Type: Amendment

#### 2. FEE ATTACHED

Amount: \_\_\_\_\_

Check No.: \_\_\_\_\_

#### 3. COMMENTS

Signed: \_\_\_\_\_

Date: \_\_\_\_\_

### B. LICENSE FEE MANAGEMENT BRANCH (Check when milestone 03 is entered / / )

1. Fee Category and Amount: \_\_\_\_\_

#### 2. Correct Fee Paid. Application may be processed for:

Amendment: \_\_\_\_\_

Renewal: \_\_\_\_\_

License: \_\_\_\_\_

#### 3. OTHER \_\_\_\_\_

Signed: \_\_\_\_\_

Date: \_\_\_\_\_