

Tennessee Valley Authority, Post Office Box 2000, Decatur, Alabama 35609-2000

Christopher M. (Chris) Crane
Vice President, Browns Ferry Nuclear Plant

May 23, 1997

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555


10 CFR 50.73

Dear Sir:

**BROWNS FERRY NUCLEAR PLANT (BFN) - UNIT 2, DOCKET NO. 50- 260
- FACILITY OPERATING LICENSE DPR - 52 - LICENSEE EVENT REPORT
50-260/97001**

The enclosed report provides details concerning a reactor scram from 100 percent power. This event resulted from a personnel error during surveillance testing. This report is submitted in accordance with 10 CFR 50.73 (a)(2)(iv) as a condition that resulted in an automatic actuation of an engineered safety feature, including the reactor protection system.

Sincerely,


C. M. Crane

cc: See page 2

1/1
Ien

040001

9706040257 970523
PDR ADDCK 05000260
S PDR



U.S. Nuclear Regulatory Commission
Page 2
May 23, 1997

Enclosure

cc Enclosure):

Mr. Mark S. Lesser, Branch Chief
U.S. Nuclear Regulatory Commission
Region II
61 Forsyth Street, S. W.
Suite 23T85
Atlanta, Georgia 30303

NRC Resident Inspector
Browns Ferry Nuclear Plant
10833 Shaw Road
Athens, Alabama 35611

Mr. J. F. Williams, Project Manager
U.S. Nuclear Regulatory Commission
One White Flint, North
11555 Rockville Pike
Rockville, Maryland 20852