



Commonwealth Edison
One First National Plaza, Chicago, Illinois
Address Reply to: Post Office Box 767
Chicago, Illinois 60690

DMB

January 13, 1986

Mr. James G. Keppler
Regional Administrator
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL. 60137

Subject: Braidwood Station Units 1 and 2
Engineering Evaluation of the Pipe
Corrosion Problem Identified in CECO.
NCR 633 - 55(e) 84-10 and Item 2
of Inspection Report 84-17
NRC Docket Nos. 50-456 and 50-457

Reference (a): L.O. DelGeorge letter to J.G. Keppler
dated January 7, 1986

Dear Mr. Keppler:

Reference (a) transmitted the Report which documents the basis for the closure of 10 CFR50.55(e) report 84-10 and Item 2 of Inspection Report 84-17. It was indicated that an additional distribution of this Report would be forthcoming. This letter accomplishes that redistribution.

One signed original and 19 copies of this letter and the attachments are submitted for your use.

Very truly yours,

Louis O. DelGeorge
Assistant Vice President

Attachments

cc: H.R. Denton-(w/attachments(5))
J.M. Taylor-(w/attachments(5))

1128K

8601230420 860113
PDR ADOCK 05000456
S PDR

IE27
JAN 16 1986