

URECO


NO. 40-3453

URANIUM REDUCTION COMPANY

Box 488 — Moab, Utah

June 12, 1962

R. F. HOLLIS  
General Manager



Mr. R. L. Kirk, Deputy Director  
Division of Licensing and Regulation  
United States Atomic Energy Commission  
Washington 25, D. C.

Dear Mr. Kirk:

In answer to your letter to Uranium Reduction Company of June 4, 1962 (DLR:DFH 40-3453), we are willing to have the condition as follows added to our license without the issuance of a formal order.

"The Licensee shall immediately notify the Director, Region IV, Division of Compliance, USAEC, Denver, Colorado, by telephone and telegraph of any failure in an earth dam retention system which results in a release of radioactive material into unrestricted areas. This requirement is in addition to the requirements of 10CFR20"

In order that Uranium Reduction Company may effectively follow this condition, please send to us the name of the Director of Region IV, Division of Compliance, and his office and home addresses and telephone numbers.

Yours very truly,

*R. F. Hollis*

R. F. Hollis  
Vice President and General Manager

RFH:lsp

cc: Mr. R. A. Young  
Mr. Mitchell Melich  
Salt Lake City Office  
Mr. R. W. Unger  
Mr. T. F. Izzo  
Mr. K. L. Olsen  
Mr. Henry G. Baty

Copy Provided  
Compliance

6/15/62

9612230389 520612  
PDR ADDCK 04003453  
C PDR



5575

