

MAR 27 1986

Lincoln University of Missouri  
ATTN: John E. Warren, Ph.D.  
Radiation Protection Officer  
Chestnut Street  
Jefferson City, MO

License No. 24-16097-01

Gentlemen:


This refers to the routine safety inspection conducted by Mr. W. P. Reichhold of this office on March 6 and 7, 1986, of activities authorized by NRC Byproduct Material License No. 24-16097-01 and to the telephone conversation concerning our findings with you on March 20, 1986.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



D. J. Sreniawski, Chief  
Nuclear Materials Safety  
Section 2

cc: DCS/RSB (RIDS)

RIII  
NR 3/24/86  
Reichhold/lt

yes  
RIII  
Sreniawski  
3/27

8604010175 860327  
REG3 LIC30  
24-16097-01 PDR

10  
IE07