



Carolina Power & Light Company

85 JUN 13 AIO: 27
Brunswick Steam Electric Plant
P. O. Box 10429
Southport, NC 28461-0429

June 10, 1985

FILE: B09-13510C
SERIAL: BSEP/85-1099

Dr. J. Nelson Grace, Administrator
U.S. Nuclear Regulatory Commission
Suite 2900
101 Marietta Street NW
Atlanta, GA 30323

BRUNSWICK STEAM ELECTRIC PLANT UNIT 1
DOCKET NO. 50-325
LICENSE NO. DPR-71
SPECIAL REPORT PER TECHNICAL SPECIFICATION 3.7.7.2 AND
PURSUANT TO TECHNICAL SPECIFICATION 6.9.2 (1-SR-85-4)

Dear Dr. Grace:

During an ongoing Unit 1 refueling/maintenance outage concurrent with power operation of Unit 2, Unit 1 and 2 LCOs were established on May 7, 1985, for fire protection deluge valve 2-FP-DV-13 to the sprinkler system of the units' common No. 1 emergency diesel generator. This was done to permit isolating the valve for replacement of a bent clapper in the valve-body housing. Due to the amount of time required to complete the involved repair, the specified 14-day time frames of the subject LCOs were exceeded by nine days and six hours.

While the subject LCOs were in effect, appropriate fire watches and backup fire suppression equipment were maintained.

Very truly yours,

C. R. Dietz, General Manager
Brunswick Steam Electric Plant

RMP/mcg

cc: NRC Document Control Desk

8507120592 850610
PDR ADOCK 05000325
S PDR

Tezz 1/0