

MAR 28 1986

Docket No. 50-409

Dairyland Power Cooperative  
ATTN: Mr. J. W. Taylor  
General Manager  
2615 East Avenue - South  
LaCrosse, WI 54601

Gentlemen:

This refers to the routine safety inspection conducted by Mr. D. E. Miller of this office on March 10-14, 1986, of activities at LaCrosse Boiling Water Reactor authorized by NRC Operating License No. DPR-45 and to the discussion of our findings with Mr. Boyd and other members of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

**Original signed by W.D. Shafer**

W. D. Shafer, Chief  
Emergency Preparedness and  
Radiological Protection Branch

Enclosures:

1. Notice of Violation
2. Inspection Report  
No. 50-409/86003(DRSS)

See Attached Distribution

RIII  
*DM*  
Miller/kst  
*yes*

RIII  
*my*  
Greger

RIII  
*peb*  
Boyd

RIN  
*W*  
Shafer

RIII  
*W*  
Schemacher

IE06  
11

8604040100 860328  
PDR ADOCK 05000409  
Q PDR

Distribution

cc w/enclosures:

J. Parkyn, Plant Superintendent

DCS/RSB (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII

John J. Duffy, Chief

Boiler Section

Ness Flores, Chairperson

Wisconsin Public Service

Commission

Spark Burmaster, Coulee

Region Energy Coalition