



Duquesne Light

Nuclear Group
P.O. Box 4
Shippingport, PA 15077-0004

Telephone (412) 393-6000

October 16, 1985

✓ Director of Nuclear Reactor Regulation
United States Nuclear Regulatory Commission
Attn: Mr. Steven A. Varga, Chief
Operating Reactors Branch No. 1
Division of Licensing
Washington, DC 20555

Reference: Beaver Valley Power Station, Unit No. 1
Docket No. 50-334, License No. DPR-66
Appendix R - Fire Protection

Gentlemen:

Attached to this forwarding letter is an updated copy of our fire protection report entitled "Updated Fire Protection Appendix R Review" for Beaver Valley Power Station - Unit No. 1. Since our original submittal report of June 30, 1982, the various issues associated with 10CFR50, Appendix R have resulted in additional correspondence (exemption requests, clarifications, etc.) which the enclosed report has incorporated. A summarized listing of the correspondence in chronological order is provided in Attachment I. This document should be helpful to your staff for the scheduled Appendix R audit in November at BVPS-Unit 1.

Should there be any questions or clarifications necessary concerning the Appendix R Report, please contact my staff.

Very truly yours,

J. J. Carey
J. J. Carey, Vice President, Nuclear

8510230009 851016
PDR ADOCK 05000334
F PDR

Attachment

A006
1/3
Revised Dist
Encls To: Reg File
Peter Tam (pm)
NRC POR
LPOR
NSIC
24X

cc: Mr. W. M. Troskoski, Resident Inspector
U. S. Nuclear Regulatory Commission
Beaver Valley Power Station
Shippingport, PA 15077

U. S. Nuclear Regulatory Commission
c/o Document Management Branch
Washington, DC 20555

U. S. Nuclear Regulatory Commission
Division of Reactor Safety
Attn: A. G. Krasopoulos
631 Park Avenue
King of Prussia, PA 19406

U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Attn: Dr. Thomas E. Murley, Regional Director
Region 1
631 Park Avenue
King of Prussia, PA 19406

Mr. Peter Tam, Project Manager
U. S. Nuclear Regulatory Commission
Phillips Building
Washington, DC 20555
- Mail Stop 438 -

Brookhaven National Labs
Attn: Tony Coppola
Building 130
Upton L.I., N.Y. 11973

ATTACHMENT I

Correspondence Summary Listing - Chronologically

June 6, 1979	NRC forwarded Safety Evaluation on APCS 9.5-1 (Amendment #18 to Tech. Specs.)
June 30, 1982	DLC submitted report on 10CFR50.48 Appendix R
October 22, 1982	DLC submitted additional information for exemption requests for Containment Area and Primary Auxiliary Building
October 28, 1982	DLC provided clarification on Appendix R report, alternate shutdown procedure and 72-hour cold shutdown time limit.
December 10, 1982	DLC submitted summary of November 30, 1982 meeting with the NRC.
December 20, 1982	DLC provided additional information on Control Room and PAB exemptions.
January 5, 1983	NRC issued Safety Evaluation on Sections III.G and L of Appendix R.
March 1, 1983	NRC issued corrections to January 5, 1983 SER
March 14, 1983	NRC grants exemptions from Appendix R requested in DLC submittal of June 30, 1982.
April 18, 1983	DLC provides information on protection of control power transformers and additional emergency lighting.
May 20, 1983	DLC provides additional information on control power transformers.
June 20, 1983	NRC approves method of protecting control power transformers.
October 19, 1983	NRC issues Generic Letter 83-33 on clarification of Appendix R issues.
December 16, 1983	DLC submits additional requests for exemptions based on Generic Letter 83-33.
May 30, 1984	DLC provided revised exemption request on structural steel.

August 30, 1984	NRC grants exemptions requested in December 16, 1983 submittal (except structural steel issue)
January 9, 1985	NRC issues Generic Letter 85-01 on clarification of Appendix R issues
January 14, 1985	DLC submits additional exemption requests and clarifications of deviations from Appendix R.
June 6, 1985	DLC submits additional information on Communications and Emergency Lighting based on Generic Letter 85-01.
July 10, 1985	DLC submits information on resolving structural steel issue.
August 28, 1985	DLC submits additional information on Emergency Lighting.