

May 8, 1997

Dr. John A. Bernard, Jr.
Director of Reactor Operations
Massachusetts Institute of Technology
Research Reactor
MITNRL-NW12
138 Albany Street
Cambridge, Massachusetts 02139

SUBJECT: NRC INSPECTION NO. 50-20/97-01

Dear Dr. Bernard:

On April 11, 1997, the NRC completed a one week inspection of the radiation protection program at the MIT research reactor. The enclosed report represents the results of that inspection.

No noncompliances or significant issues were identified. No response to this letter is required.

Your cooperation with us is appreciated.

Sincerely,

Original signed by:

Marvin M. Mendonca, Acting Director
Non-Power Reactors and Decommissioning
Project Directorate
Division of Reactor Program Management
Office of Nuclear Reactor Regulation

Docket No. 50-20
License No. R-37

Enclosure: NRC Region I Inspection Report No. 50-20/97-01

cc w/enclosures: See next page

DISTRIBUTION:

Docket File No. 50-20

PUBLIC

PDND r/f

MMendonca

TDragoun

PDND:PM

TDragoun

5/6/97

OFFICIAL RECORD COPY

DOCUMENT NAME: G:\SECY\DRAGOUN\MIT97.01

Region I

VMcCree

DScrenci

AAdams

TMichaels

PDND:LA

EMilton

5/8/97

PDoyle

Pisaac

WEresian

Sweiss

PDND:(A)D

MMendonca

5/8/97

1/1
DF01

9705130354 970508
PDR ADOCK 05000020
G PDR

NRC FILE CENTER COPY

May 8, 1997

Dr. John A. Bernard, Jr.
Director of Reactor Operations
Massachusetts Institute of Technology
Research Reactor
MITNRL-NW12
138 Albany Street
Cambridge, Massachusetts 02139

SUBJECT: NRC INSPECTION NO. 50-20/97-01

Dear Dr. Bernard:

On April 11, 1997, the NRC completed a one week inspection of the radiation protection program at the MIT research reactor. The enclosed report represents the results of that inspection.

No noncompliances or significant issues were identified. No response to this letter is required.

Your cooperation with us is appreciated.

Sincerely,

Original signed by:

Marvin M. Mendonca, Acting Director
Non-Power Reactors and Decommissioning
Project Directorate
Division of Reactor Program Management
Office of Nuclear Reactor Regulation

Docket No. 50-20
License No. R-37

Enclosure: NRC Region I Inspection Report No. 50-20/97-01

cc w/enclosures: See next page

DISTRIBUTION:

Docket File No. 50-20
PUBLIC
PDND r/f
MMendonca
TDragoun

Region I
VMcCree
DScrenci
AAdams
TMichaels

PDoyle
Pisaac
WEresian
SWeiss

PDND:PM
TDragoun
5/8/97

OFFICIAL RECORD COPY

DOCUMENT NAME: G:\SECY\DRAGOUN\MIT97.01

PDND:LA
EMilton
5/8/97

PDND:(A)D
MMendonca
5/8/97



UNITED STATES
NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20555-9001

May 8, 1997

Dr. John A. Bernard, Jr.
Director of Reactor Operations
Massachusetts Institute of Technology
Research Reactor
MITNRL-NW12
138 Albany Street
Cambridge, Massachusetts 02139

SUBJECT: NRC INSPECTION NO. 50-20/97-01

Dear Dr. Bernard:

On April 11, 1997, the NRC completed a one week inspection of the radiation protection program at the MIT research reactor. The enclosed report represents the results of that inspection.

No noncompliances or significant issues were identified. No response to this letter is required.

Your cooperation with us is appreciated.

Sincerely,

A handwritten signature in dark ink, appearing to read "Marvin M. Mendonca", is written over a horizontal line.

Marvin M. Mendonca, Acting Director
Non-Power Reactors and Decommissioning
Project Directorate
Division of Reactor Program Management
Office of Nuclear Reactor Regulation

Docket No. 50-20
License No. R-37

Enclosure: NRC Region I Inspection Report No. 50-20/97-01

cc w/enclosures: See next page

Massachusetts Institute of
Technology

Docket No. 50-20

cc:

City Manager
City Hall
Cambridge, Massachusetts 02139

Assistant Secretary for Policy
Executive Office of Energy Resources
100 Cambridge Street, Room 1500
Boston, Massachusetts 02202

Department of Environmental
Quality Engineering
100 Cambridge Street
Boston, Massachusetts 02108

Dr. O. K. Harling, Director of
the Reactor Laboratory
Massachusetts Institute of
Technology
138 Albany Street
Cambridge, Massachusetts 02139

Dr. William Vernetson
TRTR
262 Nuclear Science Center
Department of Nuclear Engineering
Science
University of Florida 32611

Dr. Robert McCunney, Director
Environmental Medical Service
Massachusetts Institute of Technology
77 Massachusetts Avenue
Room 20B-238
Cambridge, Massachusetts 02139