

Detroit
Edison

Douglas R. Gipson
Senior Vice President
Nuclear Generation

Fermi 2
6400 North Dixie Highway
Newport, Michigan 48166
(313) 586-5249

10CFR50.73

May 12, 1997
NRC-97-0051

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Reference: 1) Fermi 2
Docket No. 50-341
NRC License No. NPF-43

2) Detroit Edison Letter to NRC, NRC-97-0029, "Licensee Event
Report 97-005," dated April 7, 1997

Subject: Licensee Event Report (LER) No. 97-005, Revision 1

Pursuant to Fermi 2 License Condition 2.C.9 and 10CFR50.73(a)(2)(i)(B), Detroit Edison is submitting the enclosed LER No. 97-005, Revision 1, regarding inadequate design or consideration of circuits involved in achieving dedicated shutdown. The original LER (Reference 2) dealt with the Emergency Equipment Cooling Water (EECW) System makeup tank isolation valve interlocks potentially preventing operation of the EECW System from the Dedicated Shutdown Panel. However, due to additional discrepancies discovered in a review of the dedicated shutdown circuits performed as a corrective action from the original LER, the LER has been expanded to include these instances of affected dedicated shutdown circuits. All corrective actions related to this LER are complete.

There are no new commitments made in this LER.

9705190044 970512
PDR ADOCK 05000341
S PDR


160076



1/1
1e22

If you have any questions, please contact Norm Peterson, Compliance Supervisor, at (313) 586-4528.

Sincerely,

A handwritten signature in black ink, appearing to read "Norm Peterson".

cc: A. B. Beach
G. A. Harris
M. J. Jordan
A. J. Kugler
M. V. Yudas, Jr.
Region III
Wayne County Emergency Management Division