

OPERATING DATA REPORT

DOCKET NO. 50-366
 DATE 12-5-78
 COMPLETED BY S. Wilson
 TELEPHONE 912-367-7781

OPERATING STATUS

1. Unit Name: Hatch - 2
2. Reporting Period: November
3. Licensed Thermal Power (MWt): 2436
4. Nameplate Rating (Gross MWe): 820
5. Design Electrical Rating (Net MWe): 790
6. Maximum Dependable Capacity (Gross MWe): 820
7. Maximum Dependable Capacity (Net MWe): 790
8. If Changes Occur in Capacity Ratings (Items Number 3 Through 7) Since Last Report, Give Reasons:

Notes

9. Power Level To Which Restricted, If Any (Net MWe):
10. Reasons For Restrictions, If Any:

	This Month	Yr.-to-Date	Cumulative
11. Hours In Reporting Period	<u>720</u>	<u>1465</u>	<u>1465</u>
12. Number Of Hours Reactor Was Critical	<u>619.1</u>	<u>1269.2</u>	<u>1269.2</u>
13. Reactor Reserve Shutdown Hours	<u>0</u>	<u>0</u>	<u>0</u>
14. Hours Generator On-Line	<u>498.2</u>	<u>852.0</u>	<u>852.0</u>
15. Unit Reserve Shutdown Hours	<u>0</u>	<u>0</u>	<u>0</u>
16. Gross Thermal Energy Generated (MWH)	<u>625714</u>	<u>1101801</u>	<u>1101801</u>
17. Gross Electrical Energy Generated (MWH)	<u>177680</u>	<u>258110</u>	<u>258110</u>
18. Net Electrical Energy Generated (MWH)	<u>163387</u>	<u>229658</u>	<u>229658</u>
19. Unit Service Factor	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>
20. Unit Availability Factor	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>
21. Unit Capacity Factor (Using MDC Net)	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>
22. Unit Capacity Factor (Using DER Net)	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>
23. Unit Forced Outage Rate	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>
24. Shutdowns Scheduled Over Next 6 Months (Type, Date, and Duration of Each):			

25. If Shut Down At End Of Report Period, Estimated Date of Startup:

	Forecast	Achieved
26. Units In Test Status (Prior to Commercial Operation):		
INITIAL CRITICALITY	<u> </u>	<u>7-4-78</u>
INITIAL ELECTRICITY	<u> </u>	<u>9-22-78</u>
COMMERCIAL OPERATION	<u>12-31-78</u>	<u> </u>

(9/77)

7812150347

AVERAGE DAILY UNIT POWER LEVEL

DOCKET NO. 50-366
 UNIT Hatch-2
 DATE 12-5-78
 COMPLETED BY S. Wilson
 TELEPHONE 912-367-7781

MONTH November

DAY	AVERAGE DAILY POWER LEVEL (MWe-Net)	DAY	AVERAGE DAILY POWER LEVEL (MWe-Net)
1	<u>-13</u>	17	<u>352</u>
2	<u>-13</u>	18	<u>466</u>
3	<u>0</u>	19	<u>394</u>
4	<u>-16</u>	20	<u>312</u>
5	<u>86</u>	21	<u>364</u>
6	<u>270</u>	22	<u>428</u>
7	<u>307</u>	23	<u>120</u>
8	<u>193</u>	24	<u>140</u>
9	<u>-13</u>	25	<u>257</u>
10	<u>-9</u>	26	<u>98</u>
11	<u>16</u>	27	<u>166</u>
12	<u>269</u>	28	<u>366</u>
13	<u>388</u>	29	<u>439</u>
14	<u>315</u>	30	<u>318</u>
15	<u>396</u>	31	<u></u>
16	<u>412</u>		

INSTRUCTIONS

On this format, list the average daily unit power level in MWe-Net for each day in the reporting month. Compute to the nearest whole megawatt.

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50-366
 UNIT NAME Hatch-2
 DATE 12-5-78
 COMPLETED BY S. Wilson
 TELEPHONE 912-367-7781

REPORT MONTH November

No.	Date	Type ¹	Duration (Hours)	Reason ²	Method of Shutting Down Reactor ³	Licensee Event Report #	System Code ⁴	Component Code ⁵	Cause & Corrective Action to Prevent Recurrence
									Non-Commercial Unit In Startup Testing And Power Ascension

¹
 F: Forced
 S: Scheduled

²
 Reason:
 A-Equipment Failure (Explain)
 B-Maintenance of Test
 C-Refueling
 D-Regulatory Restriction
 E-Operator Training & License Examination
 F-Administrative
 G-Operational Error (Explain)
 H-Other (Explain)

³
 Method:
 1-Manual
 2-Manual Scram.
 3-Automatic Scram.
 4-Other (Explain)

⁴
 Exhibit G - Instructions
 for Preparation of Data
 Entry Sheets for Licensee
 Event Report (LER) File (NUREG-
 0161)

⁵
 Exhibit I - Same Source

(9/77)

NARRATIVE REPORT

HATCH 2

Nov. 1 Subcritical Rx. Scram 2-78-16 due to IRM upscale trip 2140 CST to IRM upscale trip 2140 CST

Nov. 2 Rx. Scram 2-78-17 on Rx. Low Water Level 1917 CST

Nov. 3 On Line For Loss Of Off Site Power Test 1247 CST
Rx. Scram 2-78-19 (GO-2-78-9) On LOSP Test 1510 CST

Nov. 4 Rx. Scram 2-78-18 On Rx. Low Water Level

Nov. 5 On Line 0915 CST

Nov. 6 Startup Testing

Nov. 8 Rx. Scram 2-78-20 (GO-2-78-10) Due to Vacuum Loss

Nov. 9 Cold Shutdown For Repairs

Nov. 11 On Line 1845 CSt

Nov. 12 Startup Testing

Nov. 23 Turbine Trip Fo Startup Test Rx. Scram 2-78-21 (GO-2-78-11)

Nov. 24 On Line 0504 CST

Nov. 26 Rx. Scram 2-78-22 (GO-2-78-12) due to Turbine Trip On Low EHC Oil Pressure 0705 CST

Nov. 27 On Line 0802 CSt

Nov. 28 Startup Testing

There was no single release of radioactivity or single radiation exposure which accounts for more than 10 percent of the allowable annual values during the month of November.

HATCH 2 SAFETY-RELATED MAINTENANCE REQUESTS
TO BE REPORTED FOR NOVEMBER 1978

<u>Number</u>	<u>Dated Completed</u>	<u>Description</u>
78-291	11-20-78	Install And CATE Cables Per DCR-2-78-43
1737	11-29-78	Setup 2E41-F035 For 60 PSIG Pressure Out When Normal Steam Pressure Is Available
1894	11-29-78	Reset The Time Delay Of The HPCI Turbine Overspeed Reset
2799	10-30-78	Tighten Wire Rope Restraints As Per HNP-2-10033
2852	11-25-78	Install New Seats On RWCU Pumps Per DCR-78-210
2923	11-6-78	Add Thermal Insulators Between Thermocouples And Mounting Brackets Of 2T48-0009
2951	10-30-78	Verify The Drywell Temperature Alarms Function Properly
3078	11-20-78	Install Conduits Per DCR-78-270
3192	11-3-78	Replace Cap Screws, Belleville Springs Per DCR-78-251
3279	11-4-78	Replace "O" Ring On 2C D/G Oil Strainer
3444	11-10-78	Repair RWCU MOV In Drywell Valve Leak
3456	11-13-78	Repair Broken Relay Case No 50-51A On RHR S.W. Pump 2B
3460	10-31-78	Repair The Leak Around RWCU Suction Isolation Valve
3514	10-31-78	Repair RWCU Vessel B Outlet Valve
3536	10-30-78	Repair Packing Leak Around RWCU Demin Isolation Valve

HATCH 2 SAFETY-RELATED MAINTENANCE REQUESTS
TO BE REPORTED FOR NOVEMBER 1978

<u>Number</u>	<u>Dated Completed</u>	<u>Description</u>
3538	11-6-78	Replace Broken Bulbs on 2R22-S001
3541	11-6-78	Replace Broken Bulbs on 2R22-S003
3549	11-17-78	Calibrate D/G 2A Jacket Cooling Water Indicator
3554	11-13-78	Check Calibration of RFP Discharge Flow Indicators
3555	11-6-78	Replace Broken Bulbs On 2R22-S002
3568	11-9-78	Calibrate D/G 2A Jacket Cooling Water Indicator
3643	11-8-78	Repair HPCI Steam Inlet MOV
3649	11-3-78	Repair Pretreatment Sample Pump
3654	11-16-78	REpair SW On 1B D/G Lube Oil Temp Hi/Lo Alarm
3722	10-28-78	Repair H ₂ & O ₂ Analyzer Recorder R601B
3734	11-6-78	Repair RWCu Return To Vessel Valve Steam Leak
3750	11-16-78	Repair "A" RWCu Demin Man. Vent Valve Indicator
3751	11-21-78	Repair "A" RWCu Demin AOV Vent Valve Leak
3755	11-1-78	Repair RCIC Steam Trap Leak
3779	10-10-78	Remove The Tube Spaces Per DCR-78-329, R1
3781	11-10-78	Repair Packing Leak Of Isolation Valve On RWCu Heat Exchanger
3782	11-2-78	Delete Snubber 2E11-RHR-R233

HATCH 2 SAFETY-RELATED MAINTENANCE REQUESTS
TO BE REPORTED FOR NOVEMBER 1978

3784	10-30-78	Remove Bands On Snubber Pistons 2E11-RHR-R238
3785	11-2-78	Delete Snubber 2E11-RHR-R233
3944	10-28-78	Repair Excessive Leakage of Torus D/G Vacuum Breakers
3952	11-8-78	Repair Cracked Vent Line On 2E11-F003
3956	10-29-78	Correct Stepping Sw. On RWCU Panel
3978	11-7-78	Calibrate RWCU "A" Effluent Conductivity Meter
3995	11-6-78	Repair Handwheel On 2G31-F052B
3996	11-6-78	Repair Handwheel On 2G31-F056B
4007	10-31-78	Grind Paint From Torus At Location For SG 13, 14, & 15
4019	11-17-78	Install Remote Load Meter Per DCR78-379
4021	11-22-78	Repair Indicator For MSIV LCA Outboard Isolation Valve
4025	10-30-78	Implement DCR-78-307
4027	11-18-78	Perform P/M On Standby Liquid Control Pumps
3800	10-30-78	Fabricate Orifice For RHR Discharge At Flume
3809	10-30-78	Repair Blown Pump Seal On RWCU Pump 2A
3826	10-30-78	Reset Limit Sw. Per DCR-78-314
3861	10-31-78	Replace Solenoid On 2d11-J014
3864	11-21-78	Repair RWCU Inboard Isolation Valve
3878	10-28-78	Repair RBM 2"A" & 2"B" Alarm

HATCH 2 SAFETY-RELATED MAINTENANCE REQUESTS
TO BE REPORTED FOR NOVEMBER 1978

3879	10-31-78	Change Setpoint Per HNP-7450 On 2D11-K633 & K632
3880	11-9-78	Implement DCR-78-293
3897	11-8-78	Repair Oil Leak On RCIC Turbine
3919	11-3-78	Replace D/G 2C Battery Cap
3938	10-30-78	Repair RHR Service Water Pump Leak
3939	11-3-78	Clean Filter Aid Tank Effluent Line
3942	10-31-78	Repair RHR LPCI Injection Check Valve Leak
3943	10-31-78	Repair RHR LPCI Injection Check Valve Leak
4112	10-31-78	Repair "A" RHR Lopp Min. Flow MOV
4130	11-2-78	Calibrate Jet Pump Delta P Transmitters
4037	11-2-78	Repair Indicators On RWCU A/O Valves F052A F054A
4041	10-28-78	Change Out Control Rod Select Switch 50-27
4045	11-8-78	Repair Heater Fan 2X41-B004E Thermostat
4047	11-10-78	Repair Heater Fan 2X41-B004E Thermostat
4052	11-6-78	Replace "O" Ring On 2G31-F052A
4057	11-11-78	Repair Turbine Bldg. Floor Drain Sump "Hi-Level" Alarm
4060	11-8-78	Replace Bad Sw. In RCIC controller 2E51-R612
4068	11-12-78	Repair RWCU Demin B Isolation Valve

HATCH 2 SAFETY-RELATED MAINTENANCE REQUESTS
TO BE REPORTED FOR NOVEMBER 1978

4069	11-12-78	Repair RWCU Demin B Isolation Valve
4070	11-13-78	Adjust Snubber O Torus D/W Vacuum Breaker
4076	11-6-78	Repair Packing Leaks On Vent & Drain Lines On Main Steam Lines
4088	11-3-78	Repair Packing Leak On 2N11-F004B
4093	11-6-78	Calibration Torus Press. Indicator
4094	11-20-78	Perform P/M On DC Motors per HNP-2-6563
4097	11-30-78	Perform P/M On DC Motors per HNP-2-6563
4098	10-30-78	Repack E41-F004
4100	11-3-78	Repack RHR Gate Valve
4106	11-23-78	Calibrate MSL D/P Indicator
4110	11-1-78	Calibrate Sw. Rt. Conveter For Jet Pump #7
4113	10-30-78	Rebuild RHR Sw. Pump Seal "C"
4114	11-1-78	Repair 2A RWCU Demin Isolation Valve
4127	11-16-78	Damp Scoop Positioner For 2B Recirc MG-Set
4132	11-13-78	Repair Steam leak On 2E51-D003
4133	11-1-78	Add Oil To CRD Pump Motor Oil Slinger
4131	11-22-78	Reset Logic On Hydrogen Peroxide Analyzer B
4134	11-3-78	Add Oil To CRD Pump Motor Oil slinger
4140	11-6-78	Replace Card On 2P33-P001A Instrument Failure" Alarm

HATCH 2 SAFETY-RELATED MAINTENANCE REQUESTS
TO BE REPORTED FOR NOVEMBER 1978

4143	11-13-78	Repair Hanger 2B21-F23
4155	11-16-78	Repair Indicator Light Fixture On 2G31-F068A
4170	11-2-78	Recalibrate 2E11-R003A, B, C, D per HNP-2-5504
4172	11-3-78	Calibrate 2E41-K101 per HNP-2-5213
4173	11-3-78	Calibrated 2E41_R6001 per HNP-2-5233
4190	11-2-78	Calibrate 2G31 per HNP-2-5245
4199	11-6-78	Clean Servo Booster On D/G 2C
4205	11-23-78	Perform Inservice Visual Inspection of 2C71-N003A & B
4247	11-6-78	Replace blown Fuse In Panel 2H11-P657 For HPCI Room Cooler
4252	11-8-78	Repair D/G (Engine Overspeed Alarm)
4255	11-6-78	Adjust alarm Sw. On 2448-RW23
4258	11-11-78	Repair High Conductivity Sump Pump
4259	11-29-78	Clean Snubber Pistons
4260	11-29-78	Replace Spring Clip On Snubber
4261	11-29-78	Replace Center Pin On Snubber
4262	11-7-78	Investigate Possible Leak On Snubber 2N11-MS-R54
4268	11-14-78	Repair HPCI Test Line Check Valve Leak
4277	11-13-78	Install New Sw. On 2R43-P001A
4279	11-21-78	Rebuild Valve Off Of Main Steam System
4285	11-6-78	Repair speed Switch on 2C Diesel Generator

HATCH 2 SAFETY-RELATED MAINTENANCE REQUESTS
TO BE REPORTED FOR NOVEMBER 1978

4288	11-11-78	Replace Fuse On Radwaste Control Panel Controller LCI
4290	11-21-78	Clean Seat On Relief Valve 2E11-F212B
4295	11-13-78	Repair 2A d/G Local Annunciator
4302	11-13-78	Investigate d/G fan Lowers
4308	11-6-78	Replace Aux. Control Block on 2BB1-S001B1
4310	11-15-78	Calibrate SSLC Pressure Gauge
4312	11-13-78	Change Setpoints on Rx. Bldg. Vent Rad. Monitor
4313	11-6-78	Calibrate RHR Loop Flow Indicator
4314	11-14-78	Calibrate RHR Loop flow Transmitter
4324	11-6-78	Calibrate Intake Struc. Level Ind. & Alarm
4325	11-20-78	Calibrate Delta P Transmitter Filter D001 A & B
4326	11-15-78	Calibrate Delta P Transmitter Filter D001 A & B
4327	11-20-78	Calibrate Refueling Floor To ATM Pressure
4328	11-20-78	Calibrate Intake Structure Level Indicator Alarm
4329	11-15-78	Calibrate Refueling Floor To ATM Pressure
4331	11-13-78	Calibrate Sw. Rt. Converter Per HNP-2-5011
4332	11-15-78	Investigate Failure To Trip By Pump During LOSP
4339	11-5-78	Check Calibration Of Main Steam Stop Valve Recorder

HATCH 2 SAFETY-RELATED MAINTENANCE REQUESTS
TO BE REPORTED FOR NOVEMBER 1978

4344	11-14-78	Recalibrate High Steam Flow Isolation Surdus As Per HNP Procedures
4348	11-16-78	Repair "E" APRM
4350	11-14-78	Perform Preventive Maintenance On 250 VDC inverter System
4351	11-14-78	Perform Preventive Maintenance On 250 VDC Inverter System
4352	11-20-78	Perform Preventive Maintenance on 250 VDC Inverter System
4353	11-19-78	Perform Preventive Maintenance On Diesel Generator 2R43-S001A
4356	11-14-78	Perform Preventive Maintenance On Diesel Generator A & C Lube Oil Pump & Jacket Cooling Pump Motor
4357	11-9-78	Recalibrate MSL Rad. Monitor D
4358	11-9-78	Recalibrate MSL Rad. Monitor C
4359	11-9-78	Recalibrate MSL Rad. Monitor B
4360	11-9-78	Recalibrate MSL Rad. Monitor A
4366	11-15-78	Repair RCSC MOV Min. - Flow
4370	11-13-78	Repair Turbine Control Valve
4374	11-8-78	Investigate Reactor Recirc Pump "B" Operation
4376	11-17-78	Repair HPCI Ramp Generator Signal Converter
4377	11-13-78	Replace Restriction Orifice Gasket On 2b21-D001
4392	11-13-78	Repair Packing ON RCFC Outboard Steam Isolation Valve
4394	11-20-78	Reset Recirc MG Scoop Tube Actuators

HATCH 2 SAFETY-RELATED MAINTENANCE REQUESTS
TO BE REPORTED FOR NOVEMBER 1978

4395	11-11-78	Repair Filter Aid Effluent For Floor Drain system
4395	11-22-78	Repair Off Gas Condenser Auto Drain Valve
4398	11-27-78	Repair Torus Pressure Indicator
4402	11-16-78	Investigate Main Steam To Stop Valve PSIG Recorder Operation
4403	11-13-78	Replace Drive Water Filter 2C11-D003B
4408	11-15-78	Repair Missile Door To Main Steam Line Pipe Chase Locking Mechanism
4409	11-16-78	Repair HPCI Turbine EGR
4416	11-16-78	Repair MG Set Distribution Panel Wiring
4418	11-14-78	Repair HPCI Pump Discharge Valve to CST
4421	11-16-78	Repair Indicator Lamp A RWCU Panel For Vessel 2B Inlet Isolation Valve
4424	11-20-78	Repair Relay 2C11-Z1 & 2
4425	11-16-78	Repair Bulb Socket For 4160 Volt Bus 2C
4428	11-16-78	Replace Defection Rod - Select Switch On Matrix
4430	11-13-78	Repair Packing On RHR Steam Pressure Reducing Valve
4450	11-28-78	Repair Leak On HPCI Booster Pump Seal Water Line
4469	11-21-78	Recalibrate MSL Radiation Monitors C & D
4489	11-18-78	Repair Air Inlet Valve Indication
4490	11-16-78	Reset Scram Clamp On APRM Neutron Monitoring System

HATCH 2 SAFETY-RELATED MAINTENANCE REQUESTS
TO BE REPORTED FOR NOVEMBER 1978

4491	11-13-78	Repair D/W Equipment Drain Sump Pump
4492	11-13-78	Repair 2E11 Flange Leak
4498	11-15-78	Repair alarm for HPCI Pump Suction Pressure Low
4502	12-6-78	Investigate Operation of RWCU Vessel A Plenum Vent Valve
4504	11-15-78	Repair B Recirc Pump suction Valve Indication
4607	11-21-78	Repair PSW Pump 2D
4509	11-20-78	Repair RPS Reactor Water Level Switch
4510	11-18-78	Resequence Logic On RWCU - Demin B Isolation Valve
4511	11-22-78	Resequence Logic On RWCU Demin B Isolation Valve
4517	11-22-78	Investigate operation Of Regueling Floor Vent Filter Discharge Low Rad. alarm
4520	11-20-78	Reconnect Rx. Building Vent Rad. Monitor Unit 2 able
4526	11-19-78	Repair Turb. Bldg. Vent flow Recorder
4536	11-16-78	Repair Multi Pomt Ventilation Recorder
4543	11-23-78	Repair Faulty Annunciator Alarm For CUPSA TANK HI LEVEL
4545	11-20-78	Repair control Room annunciators P601, P654
4551	11-22-78	Reset MSL Rad. Monitors A,B,C,&D
4556	11-22-78	Ground APRM A,B,C,E,E,F, And RPM A,B
4569	11-27-78	Repair Indicator Lamp Socket For #160 Volt Bus 2C

HATCH 2 SAFETY-RELATED MAINTENANCE REQUESTS
TO BE REPORTED FOR NOVEMBER 1978

4581	11-22-78	Investigate Operation Of 2A D/G Alarm Panel In Unit 2 Control Room
4587	11-27-78	Investigate Operation of 2A D/G Alarm Panel Generator Filed Ground
4588	11-22-78	Perform Preventive Maintenance on Standby liquid Control Pump & Accumulator A
4589	11-22-78	Perform Preventive Maintenance On Standby Liquid Control Pump & Accumulator B
4597	11-27-78	Repair RCIC Minimum Flow Valve
4598	11-23-78	Repair Torus Level And Drywell PSIG Recorder
4599	11-22-78	Correct Wiring Labels On Reactor Control Panel
4406	11-23-78	Repair Primary Containment Oxygen & Hydrogen Recorder
4609	11-25-78	Modify HPCI Stop Valve And Rewire
4618	11-27-78	Investigate Operation Of 2A D/G Annunciator Gen. Filed Ground
4633	11-27-78	Repair Recirc Pump Delta P Indicator
4634	11-21-78	Replace Yarway Rx. Level Indicating Level Switch
4635	11-21-78	Repair Recirc System Master Controller
4636	11-28-78	Repair Leak On HPCI Shaft Driven Oil Pump Pressure Regulator Valve
4637	11-21-78	Repair HPCI Low System Pressure Gauges
4638	11-21-78	Repair RWCU Booster Blower
4639	11-21-78	Repair PSW Screen Wash MOV

HATCH 2 SAFETY-RELATED MAINTENANCE REQUESTS
TO BE REPORTED FOR NOVEMBER 1978

4642	11-24-78	Investigate Calibration Of PSW Discharge To CCW Inlet Low Delta P Alarm
4650	11-22-78	Repair Chill Water Safety Shutdown Alarm
4656	11-22-78	Investigate Operation Of PSW Pump A Minimum Flow Valve
4659	11-22-78	Perform Preventive Maintenance On Reactor Recirculation System A
4660	11-22-78	Perform Preventive Maintenance On Reactor Recirculation System B
4674	11-24-78	Repair Turbine Bldg. Vent Flow Recorder
4677	11-27-78	Repair Butterfly Type Valve for RWCU 2G31-F092B
4685	11-23-78	Recalibrate MSL Radiation Monitors A,B,C, & D
4686	11-24-78	Repair Annunciator For 2A Diesel Generator Ground Fault
4691	11-30-78	Investigate Operation Of PSW Pump 2B Seal Water Pressure Indicator
4698	11-27-78	Reset Setpoint Of MSL A,B,C, & D
4707	11-27-78	Calibrate RHR Pump Suction Pressure Gauge
4709	11-28-78	Repair Packing On Rad. Waste Valve 2G11-F019
4720	11-28-78	Repair Packing On Nitrogen To D/W & Torus Isolation Valve
4721	11-28-78	Reset Limit Switch On Nitrogen To D/W & Torus Isolation Valve

HATCH 2 SAFETY-RELATED MAINTENANCE REQUESTS
TO BE REPORTED FOR NOVEMBER 1978

4722	11-30-78	Adjust Alarm contact For Reactor Vessel Water Level Hi Or Low Monitor
4724	11-27-78	Recalibrate Reactor Water Level Indicator
4726	11-27-78	Repair RWCU A vVessel Backwash Air Isolation Valve
4727	11-27-78	Adjust Indicator For RWCU Vessel Vent Isolation Valve
4729	11-27-78	Repair SBTG Discharge Flow Recorder
4734	11-27-78	Repair PSW Pump 2B High Seal Water Pressure
4751	11-30-78	Repair Minimum Flow PSW Pump D
4758	11-28-78	Repair RCIC Minimum Flow Valve
4760	11-28-78	Repair Yarway Wide Range Level
4761	11-29-78	Repair Rod Block Monitor
4792	11-28-78	Repair Reactor Recirc Pump A Discharge Valve
4832	11-20-78	Repair Waste Precoat Pump 2G11-C013