



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION IV  
611 RYAN PLAZA DRIVE, SUITE 1000  
ARLINGTON, TEXAS 76011

*Central file*

August 22, 1978

In Reply Refer To:  
Docket No. 50-298/78-14

Nebraska Public Power District  
ATTN: Mr. J. M. Pilant, Director  
Licensing and Quality Assurance  
P. O. Box 499  
Columbus, Nebraska 68601

Gentlemen:

This refers to the meeting conducted by Messrs. Karl V. Seyfrit, G. L. Madsen and E. H. Johnson of this office on August 18, 1978, of activities authorized by NRC Operating License DPR-46, for the Cooper Nuclear Station.

The meeting was conducted for the purpose of reviewing the inspection program conducted by the Office of Inspection and Enforcement and to discuss the licensee's enforcement history. Also discussed were items of current concern to the regional office staff. Within the scope of this meeting no items of noncompliance were identified.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If this report contains any information that you or your contractors believe to be proprietary, it is necessary that you make a written application within 20 days to this office to withhold such information from public disclosure. Any such application must include a full statement of reasons on the basis of which it is claimed that the information is proprietary, and should be prepared so that proprietary information identified in the application is contained in a separate part of the document. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

7810160056


Nebraska Public Power District

-2-

August 22, 1978

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

A handwritten signature in dark ink, appearing to read "G. L. Madsen / for".

G. L. Madsen, Chief,  
Reactor Operations and  
Nuclear Support Branch

Enclosure:

IE Inspection Report No. 50-298/78-14

cc w/enclosure:

L. C. Lessor, Superintendent  
Cooper Nuclear Station  
P. O. Box 98  
Brownville, Nebraska 68321