

License No. 35-17259-01.

Notice of Violation

Based on the results of the NRC inspection conducted on August 31, 1978, certain activities appear to be in noncompliance with the conditions of your NRC License No. 35-17259-01 as indicated below:

Contrary to License Condition 16, which requires that licensed material be used in accordance with statements contained in application dated October 22, 1975, inspection and maintenance of radiographic exposure devices was not performed at quarterly intervals as specified.

This is an infraction.

7810200263