



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION V

SUITE 202, WALNUT CREEK PLAZA  
1990 N. CALIFORNIA BOULEVARD  
WALNUT CREEK, CALIFORNIA 94596

DEC 12 1978

THIS DOCUMENT CONTAINS  
POOR QUALITY PAGES

License No. 04-17679-01E

Suncrux, Incorporated  
10440 North Tantau Avenue  
Cupertino, California 95014

Attention: Mr. Earl A. Zanger  
President

Gentlemen:

Thank you for your letter dated November 28, 1978, informing us of the steps you have taken to correct items which we brought to your attention in our letters dated November 1, 1978, and November 3, 1978. Your corrective actions will be verified during an early reinspection.

Your reply to Item C of the Notice of Violation did not state that watch markings to identify the presence of tritium and to indicate Suncrux as the manufacturer would be as shown in Drawing SK10777, included with the application dated October 6, 1977. (A copy of the drawing is enclosed for your convenience.) Please note that if the markings proposed in your letter differ from those in Drawing SK10777, you may need to amend your license to authorize the change.

Your cooperation with us is appreciated.


Sincerely,

R. H. Engelken  
Director

Enclosure: As Stated

7812260086

OCT 6 1977



MODULE TO CASE  
ASSEMBLY,  
TRITIUM

SUNCRUX

10440 NORTH TANTAU AVENUE,  
CUPERTINO, CALIFORNIA 95014

Drawing Number

GK10777

Code Ident.

Rev.

Sheet