

APPENDIX A

NOTICE OF VIOLATION

Westinghouse Electric Corporation
Youngwood, Pennsylvania 15697

Docket No. 030-06179
License No. 37-07934-01

As a result of the inspection conducted on October 14, 1987, and in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (Enforcement Policy) (1986), the following violations were identified:

Condition 13 of License No. 37-07934-01 requires that records of leak test results shall be maintained for inspection.

Contrary to the above, as of October 14, 1987, no records of leak tests since May 1985 had been maintained.

This is a Severity Level V violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, Westinghouse Electric Corporation is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

OFFICIAL RECORD COPY

ML DL WESTINGHOUSE - 0003.0.0
02/24/88

8803180131 880314
REC1 LIC30
37-07934-01 DCD