



the Alliance

THE ALLIANCE OF ARCHITECTS & ENGINEERS
RAPID CITY • WATERTOWN • SPEARFISH • GILLETTE
822 Main Street, Rapid City, SD 57701
(605) 342-9470

February 16, 1988

Ms. Joy Marshall
U. S. Nuclear Regulatory Commission Region 4
611 Ryan Plaza Drive - Suite 1000
Arlington, TX 76011

RE: License Amendment No. 2
License No. 40-18139-01

Dear Ms. Marshall:

This letter is our request for an amendment to the above referenced NRC License. An amendment is required because we have moved our office headquarters from Spearfish, South Dakota, to Rapid City, South Dakota. The following changes should be amended on the license:

- No. 2: Change license address to 822 Main Street, Rapid City, South Dakota 57701
- No. 16: Change address to 822 Main Street, Rapid City, South Dakota 57701
- No. 12: Change the Radiation Safety Officer from D. L. Bjerke to E. Dallas Wasserburger. Mr. Bjerke is now in charge of our Watertown, South Dakota, office. Delete the names of Winston Shann and Donald Jacobson from the list of employees who are licensed because they no longer work of us. Insert the names of Randy Deibert, Roy Deibert, and E. Duane Stetson. These employees have completed the Troxler Training Course, and a copy of their course certificate is enclosed.

We have also enclosed a floor plan of our building showing the storage area for the Troxler 3411-B. Also enclosed is a check for \$60 for the amendment fee.

We would appreciate your response to this as soon as possible. If you have any questions, please contact this office.

Sincerely,

ALLIANCE OF ARCHITECTS AND ENGINEERS

E. Dallas Wasserburger
E. Dallas Wasserburger, P.E. and L.S.

Enclosures

8803210439 880302
REG4 LIC30
40-18139-01 DCD

TROXLER ELECTRONIC LABORATORIES, INC.

HEREBY CERTIFIES THAT

WASSERBURGER E. DALLAS

of

BRADY CONSULTANTS, INC.

HAS SUCCESSFULLY COMPLETED THE TROXLER ELECTRONIC LABORATORIES, INC.
TRAINING COURSE FOR THE USE OF NUCLEAR TESTING EQUIPMENT.

SUBJECTS INCLUDED IN THIS COURSE WERE AS FOLLOWS:

Radiological Safety

- | | |
|--|---|
| 1. Principles and practices of radiation protection. | 5. Radioactivity measurement standardization and monitoring techniques and instruments. |
| 2. Leak testing procedures. | 6. Accident and incident procedures. |
| 3. Mathematics and calculations basic to the use and measurement of radioactivity. | 7. Procedures for nuclear gauge storage and transportation. |
| 4. Biological effects of radiation. | 8. General safety precautions. |

Gauge Operation

- | | |
|-------------------------|----------------------|
| 1. Instrument theory | 4. Field application |
| 2. Operating procedures | 5. Gauge calibration |
| 3. Maintenance | |


INSTRUCTOR

9-15-78

DATE

William F. Troxler
PRESIDENT

NUCLEAR TESTING SERVICES

HEREBY CERTIFIES THAT

E. DUANE STETSON

of

BANNER ASSOCIATES, INC.

HAS SUCCESSFULLY COMPLETED THE NUCLEAR TESTING SERVICES TRAINING
COURSE FOR THE USE OF NUCLEAR TESTING EQUIPMENT.

Subjects included in this course were as follows.

RADIOLOGICAL SAFETY

- | | |
|--|---|
| 1. Principles and practices of radiation protection. | 5. Radioactivity measurement standardization and monitoring techniques and instruments. |
| 2. Leak testing procedures. | 6. Accident and incident procedures. |
| 3. Mathematics and calculations basic to the use and measurement of radioactivity. | 7. Procedures for nuclear gauge storage and transportation. |
| 4. Biological effects of radiation. | 8. General safety precautions. |

GAUGE OPERATION

- | | |
|-------------------------|----------------------|
| 1. Instrument theory | 4. Field application |
| 2. Operating procedures | 5. Gauge calibration |
| 3. Maintenance | |

Donald C. Muir
INSTRUCTOR

3/17/87
DATE

Donald C. Muir

TROXLER ELECTRONIC LABORATORIES, INC.

HEREBY CERTIFIES THAT

ROY DEIBERT

of

ALLIANCE OF ARCHITECTS & ENGINEERS

HAS SUCCESSFULLY COMPLETED THE TROXLER ELECTRONIC LABORATORIES, INC.
TRAINING COURSE FOR THE USE OF NUCLEAR TESTING EQUIPMENT.

SUBJECTS INCLUDED IN THIS COURSE WERE AS FOLLOWS:

Radiological Safety

1. Principles and practices of radiation protection.
2. Leak testing procedures.
3. Mathematics and calculations basic to the use and measurement of radioactivity.
4. Biological effects of radiation.
5. Radioactivity measurement standardization and monitoring techniques and instruments.
6. Accident and incident procedures.
7. Procedures for nuclear gauge storage and transportation.
8. General safety precautions.

Gauge Operation

1. Instrument theory
2. Operating procedures
3. Maintenance
4. Field application
5. Gauge calibration


DON LORENZSON
INSTRUCTOR


9/23/86

DATE

No 18830


W. F. TROXLER

PRESIDENT



Also Available On
Aperture Card

Also Available On
Aperture Card



TROXLER ELECTRONIC LABORATORIES, INC.

HEREBY CERTIFIES THAT

RANDY DEIBERT

of

ALLIANCE OF ARCHITECTS & ENGINEERS

HAS SUCCESSFULLY COMPLETED THE TROXLER ELECTRONIC LABORATORIES, INC.
TRAINING COURSE FOR THE USE OF NUCLEAR TESTING EQUIPMENT.

SUBJECTS INCLUDED IN THIS COURSE WERE AS FOLLOWS:

Radiological Safety

1. Principles and practices of radiation protection.
2. Leak testing procedures.
3. Mathematics and calculations basic to the use and measurement of radioactivity.
4. Biological effects of radiation.
5. Radioactivity measurement standardization and monitoring techniques and instruments.
6. Accident and incident procedures.
7. Procedures for nuclear gauge storage and transportation.
8. General safety precautions.

Gauge Operation

1. Instrument theory
2. Operating procedures
3. Maintenance
4. Field application
5. Gauge calibration

DON LORENTZSON

INSTRUCTOR

9/23/86

DATE

NO 18829

W. F. TROXLER

PRESIDENT

NUCLEAR TESTING SERVICES
P. O. BOX 26723
SALT LAKE CITY, UTAH 84126



LETTER

REFERENCE TO:

FIRST CLASS MAIL ☐ INTER-OFFICE ☐

FOR ALLIANCE OF ARCHITECTS & ENGINEERS
822 Main St.
Rapid City, So. Dakota 57701
Attn: Mr. Wasserburger

HOW TO USE THIS

DAY/TIME

Time Saver LETTER TO SAVE TIME.

Type or write your reply in the space below. Then mail the white copy to us and keep the pink copy for your files. You'll save time and effort, and we'll have your answer much faster! Thank you.

MESSAGE

DATE: January 27, 1988

As requested, I have enclosed a copy of our N.R.C. License No. 43-17936-01 for your records, to cover the repair time when the gauge was in our possession.

A further check of our file for the repair service on your gauge s/n 5436, indicates that a leak test was not taken at that time.

Good luck with your inspection follow up, and if NTS can be of further service please let me know.

Best regards,

Don Muir

Donald E Muir NTS

BY

REPLY

DATE

BY