

**M & H**  
**M & H CONCRETE STRUCTURES, INC.**

St. Rt. 4 -- Box 107-A  
IVYDALE, WEST VIRGINIA 25113

-----  
TELEPHONE 304/286-3678

March 15, 1988

Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D.C. 20555

RE: Docket No. 030-20530  
License No. 47-21347-01

**"REPLY TO A NOTICE OF VIOLATION"**

Gentlemen:

Please find following our written response to your correspondence of March 3rd, 1988 and further identified as NRC Inspection Report No. 47-21347.01/88-01:

- A. (1) violation is correct as stated
- (2) due to the heavy work load of the technicians the gauges were in the field instead of at the shop and/or Lab
- (3) Leak Tests - Leak Tests will be taken on a five (5) month interval with a chart being kept at the gauges storage area with the information of when the last test was taken and when the next test is due. Notice will be given to the Technician, when the tests are due
- B. (1) violation is correct as stated
- (2) due to the heavy work load of the technician the gauges were not available for physical inventory at the shop and/or Lab
- (3) a physical inventory of both gauges will be taken at the same time leak tests are taken and the information will be posted on the leak test charts.
- C. (1) violation is correct as stated
- (2) Since both gauge cases has all of the shipping information on them, it was assumed that this was enough to be in compliance
- (3)a. shipping papers describing the hazardous materials have been placed in all vehicles used to haul these gauges. The papers are within arms reach, but none are in the Glove Box or any other locked area.
- b. A complete documentation of tests and an engineering

*LEO*  
1/0

C. (3)b.(continued)

evaluation of the construction methods, packaging design and materials of construction comply with that specification for both gauge cases has been received from Troxler and is at the present time on file at our Ivydale office.

c.49 CFR 173.476(a) - a complete safety analysis of the special form material for shipping has been received from Troxler and is at the present time on file at the Ivydale office.

- D. (1) violation is correct as stated  
(2) due to a mistake in communication in the office NRC-3, 10CFR19 and 10CFR20 were filed instead of posted.  
(3) form NRC-3, "NOTICE TO EMPLOYEES" has been posted at the Ivydale office and at the Gassaway lab where the gauges are now stored when not in use with a note that documents 10CFR19 and 10CFR20 can be reviewed and/or obtained at the Ivydale office.

Trusting the above is adequate to address the violations as stated, we are,

Very truly yours,

M & H CONCRETE STRUCTURES, INC.



Ronald R. Haynes  
Company Radiation Officer

RRH/blc

cc: Regional Administrator,  
Region II  
101 Marietta St., N.W.  
Atlanta, Georgia 30323

cc: M & H Nuclear File