

I.V. Systems Division

Baxter Healthcare Corporation  
of Puerto Rico  
P.O. Box 1389  
Aibonito, Puerto Rico 00705

809.735.8021

PDR

**Baxter**



BAXTER  
QUALITY  
AWARD

April 15, 1997

1995 RECIPIENT

John P. Potter, Chief  
United State Nuclear Regulatory Commission  
Region II  
Material Licensing and Inspection Branch 2  
Division of Nuclear Material and Safety  
101 Marietta Street, N. W. 2900  
Atlanta, Georgia 30323-0199

Subject: Awareness of Material License Condition No. 14 of Material License  
(NRC License 52-21175-01)

Gentlemen:

As discussed, I want to express my awareness and knowledge of Baxter-Aibonito facility's Material License No. 52-21175-01, Condition 14 stating that Baxter Healthcare Corporation, Aibonito, Puerto Rico (Licensee) is prohibited from removing, replacing, and/or disposing of sealed sources from the irradiator. In addition, we shall not perform repairs and/or alternations on the irradiator, its control console and safety systems, its shielding or any other mechanism that might affect the containment integrity of the sealed irradiator sources, the irradiator "on-off" mechanism or the physical security of the irradiation room. Unless otherwise specified in writing by the Commission, these services shall be performed only by the irradiator manufacturer or other persons specifically licensed by the Commission or an Agreement State to perform these services.

If I can be of further assistance, please do not hesitate to contact me.

Sincerely yours,

Edwin Betancourt  
Plant Manager

/cic

3019892

130078



9705130225 970415  
PDR ADOCK 03019882  
C PDR

16

ML51