



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

March 16, 1988

NRC Bulletin 88-01
TACS 65955/65956

Director of Nuclear Reactor Regulation
U S Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket Nos 50-282 License Nos. DPR-42
50-306 DPR-60

Response to NRC Compliance Bulletin 88-01 (TACS 65955/65956)

The following information is provided in response to NRC Compliance Bulletin 88-01, "Defects in Westinghouse Circuit Breakers," dated February 5, 1988.

Westinghouse DS Series circuit breakers are not used in Class IE service at the Prairie Island Nuclear Generating Plant.

Please contact us if you have any questions related to the information we have provided.

C E Larson
Vice President Nuclear Generation

c: Regional Administrator, Region III, NRC
Sr Resident Inspector, NRC
NRR Project Manager, NRC
G Charnoff

Attachment

8803220081 880316
PDR ADOCK 05000262
Q PDR

IE(1)
11

UNITED STATES NUCLEAR REGULATORY COMMISSION

NORTHERN STATES POWER COMPANY

PRAIRIE ISLAND NUCLEAR GENERATING PLANT

DOCKET NO. 50-282
50-306

RESPONSE TO NRC COMPLIANCE BULLETIN 88-01

Northern States Power Company, a Minnesota corporation, with this letter is submitting information requested by NRC Compliance Bulletin 88-01.

This letter contains no restricted or other defense information.

NORTHERN STATES POWER COMPANY

By


C E Larson

Vice President Nuclear Generation

On this 16th day of March, 1988 before me a notary public in and for said County, personally appeared C E Larson, Vice President Nuclear Generation, and being first duly sworn acknowledged that he is authorized to execute this document on behalf of Northern States Power Company, that he knows the contents thereof, and that to the best of his knowledge, information, and belief the statements made in it are true and that it is not interposed for delay.



