



1860 SPARKMAN DRIVE  
HUNTSVILLE, AL 35806

P.O. BOX 3150  
HUNTSVILLE, AL 35810

TEL. (205) 630-0596  
(205) 630-0496

(205) 837-3554

September 25, 1981

United States  
Nuclear Regulatory Commission  
Washington, D. C. 20555

Attention: License Management Branch  
Division of Fuel Cycle and Material Safety

Gentlemen:

Please renew our License No. 01-17172-01E to cover the distribution of byproduct material in quantities not to exceed the applicable quantity set forth in Section 30.71, Schedule B, 10 CFR Part 30 to persons exempt from licensing, pursuant to Section 30.18, 10 CFR Part 30.

We understand this license covers distribution only and does not cover possession of byproduct material. Our State of Alabama License No. 480, as amended, covers possession of byproduct material.

At the time of renewal, please change our business address to Micromedic Systems, Inc., Subsidiary of Rohm and Haas Company, 330 Wynn Drive, Huntsville, AL 35805. We will be starting our move in mid October 1981 and we should complete our move by mid November 1981.

According to my telephone conversation with your Mr. Paul R. Guinn on May 12, 1981, this letter is all that is required to have our license renewed. If you need any further information please let me know.

Sincerely yours,

Howard L. McGill  
Senior Engineer

HLM:dh

8801250247 870825  
NMSS LIC30  
01-17172-01E PDR