

JUN 12 1975

Docket No. 50-29

Yankee Atomic Electric Company
ATTN: Mr. G. Carl Andognini, Assistant
to the Vice President
20 Turnpike Road
Westboro, Massachusetts 01581

Gentlemen:

Our letter to you of May 13, 1975, on the subject of main steam isolation valves contained an error involving valve nomenclature. In the letter and the enclosure, the reference to a "Y-pattern globe valve" should have been "angle non-return valve." The valve failure which occurred during startup involved an angle non-return valve of the lift-check type and not a Y-pattern globe valve. Please revise your response accordingly.

Sincerely,

Original signed by:
Robert A. Purple

Robert A. Purple, Chief
Operating Reactors Branch #1
Division of Reactor Licensing

cc: See next page

THIS DOCUMENT CONTAINS
POOR QUALITY PAGES

8011050675

P

7/1/75
(4)

OFFICE	DRL:ORB#1	DRL:ORB#1				
SURNAME	ABurger:lb	RAPurple				
DATE	6/17/75	6/12/75				

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

TO: Mr. A. Schwencer

FROM: Yankee Atomic Elec. Co.
Westborough, Mass. 01581
J.L. French

DATE OF DOCUMENT

10-8-76

DATE RECEIVED

10-12-76

☒ LETTER☐ NOTORIZED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

☒ ORIGINAL☒ UNCLASSIFIED☐ COPY

3 signed 37 CC

DESCRIPTION Ltr re their 6-2-76 ltr....trans the following:

ENCLOSURE AMDT #2 to Suppl Info for the purposes of Evaluation of 10 CFR 50, App. I for YAEC.....

(40 cys encl rec'd)

PLANT NAME: Yankee Atomic

ACKNOWLEDGED

Do Not Retain

SAFETY

FOR ACTION/INFORMATION

ENVIRO

DHL 10-14-76

ASSIGNED AD:

BRANCH CHIEF:

PROJECT MANAGER:

LIC. ASST.:

(3)

SCHWENCER
BURGER
SHEPPARD

ASSIGNED AD:

BRANCH CHIEF:

PROJECT MANAGER:

LIC. ASST.:

INTERNAL DISTRIBUTION

REG FILE

NRC PDR

I & E

(2)

OELD

GOSSICK & STAFF

MIPC

CASE

HANAUER

HARLESS

SYSTEMS SAFETY

HEINEMAN

SCHROEDER

ENGINEERING

MACCARRY

KNIGHT

SIHWEIL

PAWLICKI

PLANT SYSTEMS

TEDESCO

BENAROYA

LAINAS

IPPOLITO

KIRKWOOD

OPERATING REACTORS

STELLO

SITE SAFETY &

ENVIRO ANALYSIS

DENTON & MULLER -Lt

ENVIRO TECH.

ERNST

BAILLARD

SPANGLER

SITE TECH.

GAMMILL

STIEPP

HULMAN

SITE ANALYSIS

VOLLMER

BUNCH

J. COLLINS (2)

KREGER

CONTROL NUMBER

LPDR: GREENFIELD

TIC:

NSIC:

ASLB:

ACRS 16 CYS HOLDING

NAT LAB:

REG. VIE

LA PDR

CONSULTANTS

BROOKHAVEN NAT LAB

ULRIKSON (ORNL)

10286

POOR ORIGINAL

Yankee Atomic Electric Company

-2-

JUL 2 1975

cc: Mr. Donald G. Allen, President
Yankee Atomic Electric Company
20 Turnpike Road
Westboro, Massachusetts 01581

Greenfield Public Library
402 Main Street
Greenfield, Massachusetts 01581