


# YANKEE ATOMIC ELECTRIC COMPANY



20 Turnpike Road Westborough, Massachusetts 01581

April 1, 1977

REGULATORY DOCKET FILE COPY

United States Nuclear Regulatory Commission  
Washington, D. C. 20555

Attention: Office of Nuclear Reactor Regulation

- Reference: (a) License No. DPR-3 (Docket No. 50-29)  
(b) Letter, WYR 77-30, to USNRC, dated March 21, 1977  
(c) USNRC letter to YAEC, dated January 14, 1977

Dear Sir:

Our letter, Reference (b), to your office provided an evaluation of the potential consequences of a spent fuel handling accident inside the Yankee Rowe containment building, as requested in Reference (c). An omission has been identified on the second page, first paragraph, last sentence. This sentence should read: "The calculated results for the realistic case are  $1.1 \times 10^{-4}$  rem to the thyroid and  $5.2 \times 10^{-4}$  rem whole body dose at the site boundary".

We trust this information clarifies any misunderstanding which may have arisen.

Very truly yours,

YANKEE ATOMIC ELECTRIC COMPANY

R. H. Groce  
Licensing Engineer

RHG/kg



8011060 725