

MATERIALS LICENSE

Amendment No. 03

Pursuant to the Atomic Energy Act of 1954, as amended, the Energy Reorganization Act of 1974 (Public Law 93-438), and Title 10, Code of Federal Regulations, Chapter I, Parts 30, 31, 32, 33, 34, 35, 36, 39, 40, and 70, and in reliance on statements and representations heretofore made by the licensee, a license is hereby issued authorizing the licensee to receive, acquire, possess, and transfer byproduct, source, and special nuclear material designated below; to use such material for the purpose(s) and at the place(s) designated below; to deliver or transfer such material to persons authorized to receive it in accordance with the regulations of the applicable Part(s). This license shall be deemed to contain the conditions specified in Section 183 of the Atomic Energy Act of 1954, as amended, and is subject to all applicable rules, regulations, and orders of the Nuclear Regulatory Commission now or hereafter in effect and to any conditions specified below.

Licensee

1. Keywell L.L.C.
2. P.O. Box 386
Midland, Pennsylvania 15059

In accordance with your letter dated February 7, 1997,
3. License Number 37-28609-01 is amended in its entirety to read as follows:

4. Expiration Date April 30, 2002

5. Docket or Reference No. 030-32050

6. Byproduct, Source, and/or Special Nuclear Material

7. Chemical and/or Physical Form

8. Maximum Amount that Licensee May Possess at Any One Time Under This License

A. Cadmium 109

A. Sealed source
(IPL Model AN109)

A. Not to exceed 60 millicuries each and 300 millicuries total

B. Cadmium 109

B. Sealed source
(IPL Model XFB)

B. Not to exceed 50 millicuries each and 300 millicuries total

C. Americium 241

C. Sealed source
(IPL Model GFS)

C. Not to exceed 50 millicuries each and 300 millicuries total

9. Authorized use

- A. For use in Kevex Source Model 0102 in Kevex Series 6600 x-ray fluorescence analyzers.
- B. and C. For use in Kevex Source Model 0202 in Kevex Series 6700 x-ray fluorescence analyzers.

CONDITIONS

10. Licensed material may be used only at the licensee's facilities at 10th Street, Midland, Pennsylvania and 890 Noble Drive, West Mifflin, Pennsylvania.
11. A. Licensed material shall be used by, or under the supervision of, Jack Conway, Kip Foster, Stephen Mosura, Robert Snyder, James L. Weaver, Frank Lochiatto, or Tim Campbell.
B. The Radiation Safety Officer for this license is Kip Foster.
12. Sealed sources or detector cells containing licensed material shall not be opened or sources removed from source holders or detector cells by the licensee.



100000
9706160036 970422
PDR ADOCK 03032050
C PDR

L RECORD COPY

ML 10

**MATERIALS LICENSE
SUPPLEMENTARY SHEET**

License Number

37-28609-01

Docket or Reference Number

030-32050

Amendment No. 03

13. A. Sealed sources and detector cells shall be tested for leakage and/or contamination at intervals not to exceed 6 months or at such other intervals as are specified by the certificate of registration referred to in 10 CFR 32.210, not to exceed 3 years.
- B. Notwithstanding Paragraph A of this Condition, sealed sources designed to emit alpha particles shall be tested for leakage and/or contamination at intervals not to exceed 3 months.
- C. In the absence of a certificate from a transferor indicating that a test has been made within six months prior to the transfer, a sealed source or detector cell received from another person shall not be put into use until tested.
- D. Each sealed source fabricated by the licensee shall be inspected and tested for construction defects, leakage, and contamination prior to any use or transfer as a sealed source.
- E. Sealed sources and detector cells need not be leak tested if:
- (i) they contain only hydrogen 3; or
 - (ii) they contain only a gas; or
 - (iii) the half-life of the isotope is 30 days or less; or
 - (iv) they contain not more than 100 microcuries of beta and/or gamma emitting material or not more than 10 microcuries of alpha emitting material; or
 - (v) they are not designed to emit alpha particles, are in storage, and are not being used. However, when they are removed from storage for use or transfer to another person, and have not been tested within the required leak test interval, they shall be tested before use or transfer. No sealed source or detector cell shall be stored for a period of more than 10 years without being tested for leakage and/or contamination.
- F. The test shall be capable of detecting the presence of 0.005 microcurie of radioactive material on the test sample. Records of leak test results shall be kept in units of microcuries and shall be maintained for inspection by the Commission. If the test reveals the presence of 0.005 microcurie or more of removable contamination, a report shall be filed with the U.S. Nuclear Regulatory Commission and the source shall be removed from service and decontaminated, repaired, or disposed of in accordance with Commission regulations. The report shall be filed within 5 days of the date the leak test result is known with the U.S. Nuclear Regulatory Commission, Region I, ATTN: Chief, Nuclear Materials Safety Branch, 475 Allendale Road, King of Prussia, Pennsylvania 19406. The report shall specify the source involved, the test results, and corrective action taken.

**MATERIALS LICENSE
SUPPLEMENTARY SHEET**

License Number

37-28609-01

Docket or Reference Number

030-32050

Amendment No. 03

- G. The licensee is authorized to collect leak test samples for analysis by Radiation Safety Services, Inc. Alternatively, tests for leakage and/or contamination may be performed by persons specifically licensed by the Commission or an Agreement State to perform such services.
14. The licensee shall conduct a physical inventory every 6 months to account for all sources and/or devices received and possessed under the license. Records of inventories shall be maintained for 5 years from the date of each inventory.
15. The licensee is authorized to transport licensed material in accordance with the provisions of 10 CFR Part 71, "Packaging and Transportation of Radioactive Material."
16. Except as specifically provided otherwise in this license, the licensee shall conduct its program in accordance with the statements, representations, and procedures contained in the documents, including any enclosures, listed below. The Nuclear Regulatory Commission's regulations shall govern unless the statements, representations and procedures in the licensee's application and correspondence are more restrictive than the regulations.
- A. Application dated December 26, 1990
 - B. Letter dated February 28, 1992
 - C. Letter dated June 15, 1992
 - D. Letter dated January 15, 1996
 - E. Letter dated February 7, 1997
 - F. Letter dated March 13, 1997

APR 22 1997

Date _____

For the U.S. Nuclear Regulatory Commission

ORIGINAL SIGNED BY:
JAMES M. BONDICK

By

Nuclear Materials Safety Branch
Region I
King of Prussia, Pennsylvania 19406

APR 22 1997

Mr. Ronald G. Gosteck
Vice President
Corporate Compliance
Keywell L.L.C.
P.O. Box 386
Midland, PA 15059

Dear Mr. Gosteck:

This refers to your license amendment request. Enclosed with this letter is the amended license.

Please review the enclosed document carefully and be sure that you understand and fully implement all the conditions incorporated into the amended license. If there are any errors or questions, please notify the U.S. Nuclear Regulatory Commission, Region I Office, Licensing Assistance Team, (610) 337-5093 or 5239, so that we can provide appropriate corrections and answers.

Thank you for your cooperation.

Sincerely,

ORIGINAL SIGNED BY:
JAMES M. BONDICK

James M. Bondick
Health Physicist
Division of Nuclear Materials Safety

License No. 37-28609-01
Docket No. 030-332050
Control No. 124246

Enclosure:


Amendment No. 03

DOCUMENT NAME: R:\WPS\MLTR\L3728609.01

To receive a copy of this document, indicate in the box: "C" = Copy w/o attach/encl "E" = Copy w/ attach/encl "N" = No copy

OFFICE	DNMS/RI	N	DNMS/RI				
NAME	JBondick/jmb <i>JB</i>						
DATE	04/02/97	04/ /97	04/ /97	04/ /97	04/ /97		

OFFICIAL RECORD COPY

TELEPHONE CONVERSATION RECORD	Date: 4/7/97	Time: 10 am
Mail Control No.: 124246	License No.: 37-28609-01	Docket No.: 030-32050
Person Called: R. Gosteck	Organization: Keywell, L.L.C.	Telephone Number: 773-660-2060
Person Calling: J.Bondick	Organization: NRC	Telephone Number: 6951
Subject: Verification of list of authorized users.		
Summary: Went over the list of authorized users on the license. Gosteck stated that the name of James W. Lawrence should be removed from the list of authorized users.		
Action Required/Taken: Note to file; prepare license amendment		
Signature: J. Bondick 		Date: 4/7/97

OFFICIAL RECORD COPY

March 13, 1997

MS 16
Q-6

Mr. James M. Bondick
Health Physicist
Division of Nuclear Materials Safety

RE: LICENSE NO. 37-28609-01
Docket No. 030-32050
Control No. 124246

Dear Mr. Bondick:

This is in reply to your letter requesting additional information.

1. An application was forwarded with a management signature on February 7, 1997 after receipt of a post card from the Licensing Assistance Team Leader. A confirmation of receipt at your office was received here on February 21, 1997. Another copy is attached to this letter. Sorry for the administrative mix up.
2. The source from the Kevex 6600 at the Midland Division will be removed and disposed of by Kevex Corporation. The Kevex 6600 itself is being transferred to our Vac Air Division in Frewsburg, NY to be used for spare parts.
 - a. We will still have a Kevex 6700 x-ray fluorescence analyzer at the West Mifflin Division.
 - b. We are not requesting any change to items 6.A., 7.A., 8.A. or 9.A. as we would like to retain the option to return to a source driven unit if we should determine that the tube system does not meet our analytical requirements.

124246



Institute
of Scrap
Recycling
Industries, Inc.

OFFICIAL RECORD COPY

ML 10

MAR 17 1997 KEYWELL L.L.C.


11900 South Cottage Grove Avenue
Chicago, IL 60628
(773) 660-2060
FAX (773) 660-2064

We understand the records retention requirement regarding source inventory and the disposal of the source.

3. The training detailed in the June 15, 1992 letter was designed for our Radiation Safety Officers. Our request is to designate Messrs. Frank Lochiatto and Tim Campbell as *authorized users*. As such, their training has consisted of on the job operation under the supervision of the current authorized users for the past four years and a video training sessions which covered basic radiation principles of:
 - a. Natural versus man-made radiation.
 - b. Biological effects of radiation.
 - c. Radiation risks.
 - d. Exposure: distance, time and shielding principles.
 - e. Radiation safety and emergency response.
4. *Additional request to amend:* Since Midland will not have a source, and West Mifflin will retain a Kevex 6700 with a source, we request to replace Stephen Mosura with Kip Foster as the Radiation Safety Officer for this license. Kip has been an authorized user and underwent the training detailed in the June 15, 1992 letter on October 30, 1992 under the direction of Robert Gallagher of Applied Health Physics, Inc. of Bethel Park, PA.

Thank you for your assistance.

Sincerely,



Ronald G. Gostek
VP, Corporate Compliance

February 7, 1997

Mr. John D. Kinneman, Chief
Nuclear Materials Safety Branch 2
Division of Nuclear Materials Safety
U.S. Nuclear Regulatory Commission, Region I
475 Allendale Road
King of Prussia, PA 19406-1415

RE: LICENSE NUMBER 37-28609-01

Dear Mr. Kinneman:


We are decommissioning our source driven Kevex 6600 x-ray fluorescence analyzer located at 10th Street, Midland, PA, and replacing it with an x-ray tube system. Kevex Corporation will remove the source for disposal.

We would like to amend our license in the following manner:

1. Kip Foster shall be the Radiation Safety Officer. Kip is the General Manager of the West Mifflin facility and has undergone the same radiation safety training as had the current RSO Steve Mosura.
2. Thomas Bertrand, newly appointed General Manager of the Midland facility, shall be the new facility contact.
3. Frank Lochiatto and Tim Campbell shall be listed as authorized users. Frank and Tim have undergone the same training as the current authorized users and have been operating the Kevex under their direction for the past two years.

Please advise as to any additional license requirements pertaining to the operation of an x-ray fluorescence analyzer that uses a an x-ray tube to run the system.

Sincerely,



Ronald G. Gostek
VP, Corporate Compliance



Institute
of Scrap
Recycling
Industries, Inc.

KEYWELL L.L.C.

11900 South Cottage Grove Avenue
Chicago, IL 60628
(773) 660-2060
FAX (773) 660-2064

LICENSE FEE REQUIREMENTS

LICENSE FEE AND DEBT COLLECTION BRANCH
DIVISION OF ACCOUNTING AND FINANCE
OFFICE OF THE CONTROLLER
U.S. NUCLEAR REGULATORY COMMISSION
WASHINGTON, DC 20555-0001KEYWELL L.L.C.
ATTN: RONALD G. GOSTEK
V.P., CORPORATE COMPLIANCE
11900 SOUTH COTTAGE GROVE AVENUE
CHICAGO, IL 60628

TYPE OF ACTION

- ☐ NEW LICENSE
- ☐ RENEWAL OF LICENSE
- ☒ AMENDMENT TO LICENSE

REQUESTED DATE

2-7-97

LICENSE NUMBER

37-28609-01

CONTROL NUMBER

124246

I. APPLICATION FEE DUE

Your request for a licensing action is subject to the fee(s) in the category(ies) noted below in accordance with Section 170.31 of the enclosed Federal Register notice. Payment of the fee is required prior to the issuance of the license, renewal, or amendment.

FEE CATEGORY	APPLICATION	RENEWAL	AMENDMENT
3P	\$	\$	\$ 300.00
	\$	\$	\$
	\$	\$	\$
	\$	\$	\$
	\$	\$	\$
	\$	\$	\$
	\$	\$	\$
	\$	\$	\$
	\$	\$	\$
	\$	\$	\$

FEE(s) DUE	\$	300.00
PAYMENT RECEIVED	\$	0.00
AMOUNT DUE	\$	300.00

☒ Your request was received without the prescribed application fee.

☐ We received your Check No. _____ in the amount of \$ _____. Payment of the additional fee noted above is required.

☐ Your request will increase the scope of your license program. Therefore, your request is subject to the application fee(s) noted above. Refer to Section 170.31 and Footnote 1(d)(2).

☐ Your license expired prior to the receipt of your application for renewal. Therefore, your request is subject to the application fee(s) noted above. Refer to Section 170.31 and Footnote 1(a).

MAKE PAYMENT OF THE FEE(S) TO THE U.S. NUCLEAR REGULATORY COMMISSION AND MAIL THE PAYMENT TO THE ADDRESS LISTED AT THE TOP OF THIS FORM. IF WE DO NOT RECEIVE A REPLY FROM YOU WITHIN 30 CALENDAR DAYS FROM THE DATE LISTED BELOW, WE SHALL ASSUME THAT YOU DO NOT WISH TO PURSUE YOUR APPLICATION AND WILL VOID THIS ACTION.

II. FEE NOT REQUIRED

☐ Enclosed is Check No. _____ which accompanied your request. The fee is not required because:

☐ We received your Check No. _____ in payment of the fee.

☐ The Licensing staff has informed us that your request is to be considered as a continuation of your request dated _____, Control No. _____.

☐ Your request was combined, prior to review, with your request, Control No. _____.

III. CHECK RETURNED

☐ Enclosed is Check No. _____ which was returned to us by the bank for:

- ☐ INSUFFICIENT FUNDS
- ☐ ACCOUNT CLOSED
- ☐ OTHER

MAIL THE REPLACEMENT CHECK TO THE ADDRESS LISTED AT THE TOP OF THIS FORM AND REFERENCE THE ABOVE CONTROL NUMBER.

IV. LICENSE ISSUED WITHOUT THE REQUIRED FEE

☐ License No. _____ Amendment No. _____, issued on _____, was issued without the required fee being collected. The fee required is noted in Section I of this form.

☐ The scope of your licensed program was increased. Therefore, your request is subject to the application fee(s) noted in Section 1 of this form. Refer to Section 170.31 and Footnote 1(d)(2).

☐ Because of the urgency of your request, the license was issued without remittance of the prescribed fee noted in Section 1 of this form.

SIGNATURE -- LICENSE FEE ANALYST

LFDCB

LFDCB

Distribution:

DATE

BRENDA BROWN 301-415-6055

3/10/97

Region I
Pending
BBrown
LFARL R/F
OC/DAF R/F
OC/DAF S/P (LF-3.2.7)

3-10-97

FEB 20 1997

License No. 37-28609-01
Docket No. 030-32050
Control No. 124246

Mr. Ronald G. Gosteck
Vice President
Corporate Compliance
Keywell L.L.C.
P.O. Box 386
Midland, PA 15059

Dear Mr. Gosteck:

This is in reference to your letter dated February 7, 1997 requesting an amendment to Nuclear Regulatory Commission License No. 37-28609-01. In order to continue our review, we need the following additional information:

1. Your application was forwarded without a management signature. Please resubmit the letter signed by a management representative. Note also that a management representative should sign all future correspondence that requests a change in your license.
2. It is not clear whether both the Kevex Series 6600 fluorescence analyzer and source are being returned to Kevex Corporation, or if the source is being removed and being replaced with an x-ray tube.
 - a. Do you possess more than one Model 6600 that uses a radioactive source?
 - b. Are you requesting the deletion of Items 6.A, 7.A., 8.A, and 9.A. from your license? Note that when the source from the Kevex 6600 x-ray fluorescence analyzer is returned to Kevex Corporation, you will need to keep information in regard to the disposition of this source in your records. This information includes the Model number and serial number of the source and the date when Kevex Corporation received, or took possession of the source.
3. In order to list Mr. Frank Lochiatto and Mr. Tim Campbell as authorized users on the license, please provide: 1) the date(s) when Mr. Frank Lochiatto and Mr. Tim Campbell received the training described in your letter dated June 15, 1992, 2) the duration of the training, and 3) the name of the instructors who provided the training.

OFFICIAL RECORD COPY ML 10

R. Gosteck
Keywell, L.L.C.

-2-

The use of x-ray tubes is not subject to licensing by the NRC. Therefore, you may procure and use it without amendment to your NRC material license. However, you should contact your State regulatory authorities to determine the State licensing or registration requirements for use of an x-ray tube in the system. We will continue our review upon receipt of this information. Please reply in duplicate to my attention at the Region I Office and refer to Mail Control No. 124246. If you have any technical questions regarding this deficiency letter, please call James M. Bondick at (610) 337-6951.

If we do not receive a reply from you within 30 calendar days from the date of this letter, we shall assume that you do not wish to pursue your application.

Sincerely,

Original Signed By:

James M. Bondick
Health Physicist
Division of Nuclear Materials Safety

License No. 37-28609-01
Docket No. 030-32050
Control No. 124246

Enclosure:
10 CFR Part 20

DOCUMENT NAME: R:\WPS\DLTR\D3728609.01

To receive a copy of this document, indicate in the box: "C" = Copy w/o attach/encl "E" = Copy w/ attach/encl "N" = No copy

OFFICE	DNMS/RI	<input checked="" type="checkbox"/> N	DNMS/RI	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
NAME	JBondick/jmb	<i>JB</i>					
DATE	02/20/97	02/ /97	02/ /97	02/ /97	02/ /97	02/ /97	02/ /97

OFFICIAL RECORD COPY

February 7, 1997

Mr. John D. Kinneman, Chief
Nuclear Materials Safety Branch 2
Division of Nuclear Materials Safety
U.S. Nuclear Regulatory Commission, Region I
475 Allendale Road
King of Prussia, PA 19406-1415

030-32050

RE: LICENSE NUMBER 37-28609-01

Dear Mr. Kinneman:

We are decommissioning our source driven Kevex 6600 x-ray fluorescence analyzer located at 10th Street, Midland, PA, and replacing it with an x-ray tube system. Kevex Corporation will remove the source for disposal.

We would like to amend our license in the following manner:

1. Kip Foster shall be the Radiation Safety Officer. Kip is the General Manager of the West Mifflin facility and has undergone the same radiation safety training as had the current RSO Steve Mosura.
2. Thomas Bertrand, newly appointed General Manager of the Midland facility, shall be the new facility contact.
3. Frank Lochiatto and Tim Campbell shall be listed as authorized users. Frank and Tim have undergone the same training as the current authorized users and have been operating the Kevex under their direction for the past two years.

Please advise as to any additional license requirements pertaining to the operation of an x-ray fluorescence analyzer that uses an x-ray tube to run the system.

Sincerely,

Ronald G. Gostek
VP, Corporate Compliance

1 2 4 2 4 6

FEB 10 1997

KEYWELL L.L.C.



Institute
of Scrap
Recycling
Industries, Inc.

OFFICIAL RECORD COPY

ML 10

11900 South Cottage Grove Avenue
Chicago, IL 60628
(773) 660-2060
FAX (773) 660-2064

LICENSE FEE REQUIREMENTS

LICENSE FEE AND DEBT COLLECTION BRANCH
DIVISION OF ACCOUNTING AND FINANCE
OFFICE OF THE CONTROLLER
U.S. NUCLEAR REGULATORY COMMISSION
WASHINGTON, DC 20555-0001KEYWELL L.L.C.
ATTN: RONALD G. GOSTEK
V.P., CORPORATE COMPLIANCE
11900 SOUTH COTTAGE GROVE AVENUE
CHICAGO, IL 60628

TYPE OF ACTION

- ☐ NEW LICENSE
- ☐ RENEWAL OF LICENSE
- ☒ AMENDMENT TO LICENSE

REQUESTED DATE

2-7-97

LICENSE NUMBER

37-28609-01

CONTROL NUMBER

124246

I. APPLICATION FEE DUE

Your request for a licensing action is subject to the fee(s) in the category(ies) noted below in accordance with Section 170.31 of the enclosed Federal Register notice. Payment of the fee is required prior to the issuance of the license, renewal, or amendment.

FEE CATEGORY	APPLICATION	RENEWAL	AMENDMENT
3P	\$	\$	\$ 300.00
	\$	\$	\$
	\$	\$	\$
	\$	\$	\$
	\$	\$	\$
	\$	\$	\$
	\$	\$	\$
	\$	\$	\$
	\$	\$	\$
	\$	\$	\$

FEE(s) DUE	\$	300.00
PAYMENT RECEIVED	\$	0.00
AMOUNT DUE	\$	300.00

- ☒ Your request was received without the prescribed application fee.
- ☐ We received your Check No. _____ in the amount of \$ _____. Payment of the additional fee noted above is required.
- ☐ Your request will increase the scope of your license program. Therefore, your request is subject to the application fee(s) noted above. Refer to Section 170.31 and Footnote 1(d)(2).
- ☐ Your license expired prior to the receipt of your application for renewal. Therefore, your request is subject to the application fee(s) noted above. Refer to Section 170.31 and Footnote 1(a).

MAKE PAYMENT OF THE FEE(S) TO THE U.S. NUCLEAR REGULATORY COMMISSION AND MAIL THE PAYMENT TO THE ADDRESS LISTED AT THE TOP OF THIS FORM. IF WE DO NOT RECEIVE A REPLY FROM YOU WITHIN 30 CALENDAR DAYS FROM THE DATE LISTED BELOW, WE SHALL ASSUME THAT YOU DO NOT WISH TO PURSUE YOUR APPLICATION AND WILL VOID THIS ACTION.

II. FEE NOT REQUIRED

- ☐ Enclosed is Check No. _____ which accompanied your request. The fee is not required because:
- ☐ We received your Check No. _____ in payment of the fee.
- ☐ The Licensing staff has informed us that your request is to be considered as a continuation of your request dated _____, Control No. _____.
- ☐ Your request was combined, prior to review, with your request, Control No. _____.

III. CHECK RETURNED

- ☐ Enclosed is Check No. _____ which was returned to us by the bank for:
- ☐ INSUFFICIENT FUNDS
- ☐ ACCOUNT CLOSED
- ☐ OTHER

MAIL THE REPLACEMENT CHECK TO THE ADDRESS LISTED AT THE TOP OF THIS FORM AND REFERENCE THE ABOVE CONTROL NUMBER.

IV. LICENSE ISSUED WITHOUT THE REQUIRED FEE

- ☐ License No. _____, Amendment No. _____, issued on _____, was issued without the required fee being collected. The fee required is noted in Section I of this form.
- ☐ The scope of your licensed program was increased. Therefore, your request is subject to the application fee(s) noted in Section I of this form. Refer to Section 170.31 and Footnote 1(d)(2).
- ☐ Because of the urgency of your request, the license was issued without remittance of the prescribed fee noted in Section I of this form.

SIGNATURE -- LICENSE FEE ANALYST

LFDCB

LFDCB

Distribution:

Region I LFARE R/F

Pending OC/DAF R/F

BBrown OC/DAF S/F (LF-3.2.7)

DATE

BRENDA BROWN 301-415-6055

3/10/97

3-10-97

BETWEEN:

LICENSE FEE MANAGEMENT BRANCH, ARM
AND
REGIONAL LICENSING SECTIONS

(FOR LFMS USE)
INFORMATION FROM LTS

PROGRAM CODE: 03122
STATUS CODE: 0
FEE CATEGORY: 3P
EXP. DATE: 20020430
FEE COMMENTS:
DECOM FIN ASSUR REQD: N

LICENSE FEE TRANSMITTAL

A. REGION I

1. APPLICATION ATTACHED

APPLICANT/LICENSEE: KEYWELL L.L.C.
RECEIVED DATE: 970210
DOCKET NO: 3032050
CONTROL NO.: 124246
LICENSE NO.: 37-28609-01
ACTION TYPE: AMENDMENT

2. FEE ATTACHED

AMOUNT: -----
CHECK NO.: -----

3. COMMENTS

SIGNED
DATE

M. A. Perkins
2/10/97

B. LICENSE FEE MANAGEMENT BRANCH (CHECK WHEN MILESTONE 03 IS ENTERED 1)

1. FEE CATEGORY AND AMOUNT: 3P \$300

2. CORRECT FEE PAID. APPLICATION MAY BE PROCESSED FOR:

AMENDMENT ✓
RENEWAL -----
LICENSE -----

3. OTHER -----

SIGNED
DATE

I(97)
Log Feb 13
Rem # 832205
Check No. 8300
Amount 3P
Fee Category Amo
Type of Fee 4/1/97
Date Completed GA
By

February 7, 1997

Mr. John D. Kinneman, Chief
Nuclear Materials Safety Branch 2
Division of Nuclear Materials Safety
U.S. Nuclear Regulatory Commission, Region I
475 Allendale Road
King of Prussia, PA 19406-1415

030-32050

RE: LICENSE NUMBER 37-28609-01

Dear Mr. Kinneman:

We are decommissioning our source driven Kevex 6600 x-ray fluorescence analyzer located at 10th Street, Midland, PA, and replacing it with an x-ray tube system. Kevex Corporation will remove the source for disposal.

We would like to amend our license in the following manner:

1. Kip Foster shall be the Radiation Safety Officer. Kip is the General Manager of the West Mifflin facility and has undergone the same radiation safety training as had the current RSO Steve Mosura.
2. Thomas Bertrand, newly appointed General Manager of the Midland facility, shall be the new facility contact.
3. Frank Lochiatto and Tim Campbell shall be listed as authorized users. Frank and Tim have undergone the same training as the current authorized users and have been operating the Kevex under their direction for the past two years.

Please advise as to any additional license requirements pertaining to the operation of an x-ray fluorescence analyzer that uses a an x-ray tube to run the system.

Sincerely,

Ronald G. Gostek

Ronald G. Gostek
VP, Corporate Compliance

124246

FEB 21 1997

KEYWELL L.L.C.



Institute
of Scrap
Recycling
ISRI Industries, Inc.

OFFICIAL RECORD COPY

ML 10

11900 South Cottage Grove Avenue
Chicago, IL 60628
(773) 660-2060
FAX (773) 660-2064

This is to acknowledge the receipt of your letter/application dated

2/7/97, and to inform you that the initial processing which includes an administrative review has been performed. 37-28609-01

☐ There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

☒ Please provide to this office within 30 days of your receipt of this card

A SIGNED COPY OF YOUR LETTER DATED 2/7/97.

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned Mail Control Number **124248**
When calling to inquire about this action, please refer to this control number.
You may call us on (610) 337-5398, or 337-5260.

NRC FORM 532 (R)
(5-88)

Sincerely,
Licensing Assistance Team Leader