



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV
511 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-8064

JUN 23 1997

C. Randy Hutchinson, Vice President
Operations
Arkansas Nuclear One
Entergy Operations, Inc.
1448 S.R. 333
Russellville, Arkansas 72801-0967

SUBJECT: NRC INSPECTION REPORT 50-313/97-13; 50-368/97-13 AND NOTICE OF
VIOLATION AND NOTICE OF DEVIATION

Dear Mr. Hutchinson:

An NRC inspection was conducted May 12-16 and June 2-5, 1997, at your Arkansas Nuclear One, Units 1 and 2, reactor facilities, with in-office inspection and followup conducted during May 19-29, 1997. An exit meeting was conducted on June 5, 1997, with Mr. R. Edington and other members of your staff. The enclosed report presents the scope and results of that inspection.

The inspection identified a violation. The violation pertained to your failure to include all required ASME Code valves in the inservice test program and a failure to verify the ability of other valves, which were included in the inservice test program, to fulfill their closed safety function. This violation is of concern because of your failure to recognize that testing was required in order to maintain a valid double isolation configuration.

The inspection also identified a deviation. We are concerned about the deviation because it indicates a failure to meet commitments, and to make notification after identifying that failure.

The violation is cited in the enclosed Notice of Violation (Notice) and the circumstances surrounding the violation are described in detail in the enclosed report. The deviation is cited in the enclosed Notice of Deviation, and the circumstances surrounding the deviation are described in detail in the enclosed report. Please note that you are required to respond to this letter and should follow the instructions specified in the enclosed Notices when preparing your response. The NRC will use your response, in part, to determine whether further enforcement action is necessary to ensure compliance with regulatory requirements.

020009




9707020357 970628
PDR ADOCK 05000313
G PDR

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, its enclosure(s), and your response will be placed in the NRC Public Document Room (PDR). To the extent possible, your response should not include any personal privacy, proprietary, or safeguards information so that it can be placed in the PDR without redaction.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,


fn Arthur T. Howell III, Director
Division of Reactor Safety

Docket Nos.: 50-313; 50-368

License Nos.: DPR-51; NPF-6

Enclosures:

1. Notice of Violation
2. Notice of Deviation
3. NRC Inspection Report
50-313/97-13; 50-368/97-13

cc w/enclosures:

Executive Vice President
& Chief Operating Officer
Entergy Operations, Inc.
P.O. Box 31995
Jackson, Mississippi 39286-1995

Vice President
Operations Support
Entergy Operations, Inc.
P.O. Box 31995
Jackson, Mississippi 39286

Manager, Washington Nuclear Operations
ABB Combustion Engineering Nuclear
Power
12300 Twinbrook Parkway, Suite 330
Rockville, Maryland 20852

County Judge of Pope County
Pope County Courthouse
Russellville, Arkansas 72801

Winston & Strawn
1400 L Street, N.W.
Washington, D.C. 20005-3502

David D. Snellings, Jr., Director
Division of Radiation Control and
Emergency Management
Arkansas Department of Health
4815 West Markham Street, Mail Slot 30
Little Rock, Arkansas 72205-3867

Manager
Rockville Nuclear Licensing
Framatome Technologies
1700 Rockville Pike, Suite 525
Rockville, Maryland 20852

E-Mail report to T. Boyce (THB)
 E-Mail report to NRR Event Tracking System (IPAS)
 E-Mail report to Document Control Desk (DOCDESK)
 E-Mail report to Richard Correia (RPC)
 E-Mail report to Frank Talbot (FXT)

bcc to DCD (IE01)

bcc distrib. by RIV:

Regional Administrator
 DRP Director
 Branch Chief (DRP/C)
 Project Engineer (DRP/C)
 Branch Chief (DRP/TSS)

Resident Inspector
 MIS System
 RIV File
 DRS-PSB

DOCUMENT NAME: R:_ANO\AN713RP.LEE

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:RI:MB	E	RI:MB		NRR:MEB		C:MB	E	D:DRP		D:DRS	
LEEIlershaw/lmb*		WMMcNeill*		YSHuang*		DAPowers		TPGwynn		ATHowell	
06/ /97		06/ /97		06/ /97		06/25/97		06/26/97		06/28/97	

*previously concurred

OFFICIAL RECORD COPY

E-Mail report to T. Boyce (THB)
 E-Mail report to NRR Event Tracking System (IPAS)
 E-Mail report to Document Control Desk (DOCDESK)

bcc to DCD (IE01)

bcc distrib. by RIV:

Regional Administrator
 DRP Director
 Branch Chief (DRP/C)
 Project Engineer (DRP/C)
 Branch Chief (DRP/TSS)

Resident Inspector
 MIS System
 RIV File
 DRS-PSB

DOCUMENT NAME: R:_ANO\AN713RP.LEE

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:RI:MB <input checked="" type="checkbox"/>	RI:MB <input checked="" type="checkbox"/>	NRR:MEB	C:MB <input checked="" type="checkbox"/>	D:DRP	D:DRS
LEEIershaw	WMMcNeill	YSHuang	DAPowers	TPGwynn	ATHowell
06/19/97	06/19/97	06/20/97 E-MAIL	06/ /97	06/ /97	06/ /97

OFFICIAL RECORD COPY

E-Mail report to T. Boyce (THB)
 E-Mail report to NRR Event Tracking System (IPAS)
 E-Mail report to Document Control Desk (DOCDESK)
 E-Mail report to Richard Correia (RPC)
 E-Mail report to Frank Talbot (FXT)

bcc to DCD (IE01)

bcc distrib. by RIV:

Regional Administrator
 DRP Director
 Branch Chief (DRP/C)
 Project Engineer (DRP/C)
 Branch Chief (DRP\TSS)

Resident Inspector
 MIS System
 RIV File
 DRS-PSB

DOCUMENT NAME: R:_ANO\AN713RP.LEE

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:RI:MB	E	RI:MB		NRR:MEB		C:MB	E	D:DRP		D:DRS	
LEEIlershaw/lmb*		WMMcNeill*		YSHuang*		DAPowers		TPGwynn		ATHowell	
06/ /97		06/ /97		06/ /97		06/15/97		06/16/97		06/15/97	

*previously concurred

OFFICIAL RECORD COPY