



THE ORTOPEDIC SPECIALTY HOSPITAL (TOSH)

November 6, 2020

Director of NMSS

Attn: 

U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

RE: TRANSFER NOTIFICATION LETTER

Facility Name(s): Cottonwood Hospital [Utah Radioactive Material License Terminated on 04/16/08]; and IHC Health Services, Inc. d.b.a. The Orthopedic Specialty Hospital (TOSH)


NOTE: TOSH was a part of Cottonwood Hospital and after the license was terminated, TOSH became the surviving entity. The location of use did not change. Both facilities were/are owned by IHC Health Services, Inc.

To Whom It May Concern:

In fulfillment of the requirements of Utah Radiation Control Rule R313-21-22(4), we hereby notify you that on 10/16/20 we transferred the self-luminous exit signs listed on the attached spreadsheets to SRB Technologies Inc. 2580 Landmark Dr. Winston-Salem, NC 2710; North Carolina License # 034-0634-2. The receipt of the exit signs was confirmed on 10/22/20. As required, for each sign listed on the spreadsheet we include the name of the manufacturer, model number, and serial number. NOTE: The Utah Division of Waste Management and Radiation Control has also been sent a similar letter.

If you should have any questions, please contact me.

Respectfully,



Julie Rupp Felice, CPM, Health Physicist
Director of Radiation Safety, Radiation Safety Officer
Intermountain Healthcare, Inc.
(801) 507-7951; julie.felice@imail.org
Cell: 801-634-2994



This Serial Number Log must also accompany each box as a packing slip and so must accurately reflect the inventory of EACH box.

Inventory Box Number: 1 of 4

Line	Manufacturer Name	Model Number	Serial Number	Date of Manufacture	Activity (Ci or TBq amount)
1	Shield Source Inc.	SLX-60	13-12851	4413	0.281 TBq
2	Shield Source Inc.	SLX-60	13-12850	4413	0.281 TBq
3	Shield Source Inc.	SLX-60	13-12848	4413	0.281 TBq
4	Isolite	2040	231028	07/03	7.5 Ci
5	Shield Source Inc.	SLX-60	13-12849	4413	0.281 TBq
6	Shield Source Inc.	SLX-60	13-12846	4413	0.281 TBq
7	Shield Source Inc.	SLX-60	13-12839	4413	0.281 TBq
8	Shield Source Inc.	SLX-60	13-12845	4413	0.281 TBq
9	Shield Source Inc.	SLX-60	13-12852	4413	0.281 TBq
10	Shield Source Inc.	SLX-60	13-12853	4413	0.281 TBq

JF
Initial

10/9/20
Date

Please email this log to sales@tritiumdisposal.com or fax to: 614-863-0622.
Make sure to include your contact info if you have not already been assigned a TritiumDisposal account rep.



This Serial Number Log must also accompany each box as a packing slip and so must accurately reflect the inventory of EACH box.

Inventory Box Number: 2 of 4

Line	Manufacturer Name	Model Number	Serial Number	Date of Manufacture	Activity (Ci or TBq amount)
1	SRB Technologies	B100	685563	04/04	20 Ci
2	Isolite	2040	234836	08/03	7.5 Ci
3	Isolite	2040	234808	08/03	7.5 Ci
4	Isolite	2040	234811	08/03	7.5 Ci
5	Isolite	2040	234810	08/03	7.5 Ci
6	Isolite	2040	230272	07/03	7.5 Ci
7	Isolite	2040	231023	07/03	7.5 Ci
8	Isolite	2040	231025	07/03	7.5 Ci
9	Shield Source Inc.	SLX-60	13-12842	4413	0.281 TBq
10	Shield Source Inc.	SLX-60	13-12843	4413	0.281 TBq

JF
Initial

10/9/20
Date

Please email this log to sales@tritiumdisposal.com or fax to: 614-863-0622.
Make sure to include your contact info if you have not already been assigned a TritiumDisposal account rep.



This Serial Number Log must also accompany each box as a packing slip and so must accurately reflect the Inventory of EACH box.

Inventory Box Number: 3 of 4

Line	Manufacturer Name	Model Number	Serial Number	Date of Manufacture	Activity (Ci or TBq amount)
1	Isolite	2040	249581	1/04	7.5 Ci
2	SRB Technologies	B-100	612984	1/97	20 Ci
3	SRB Technologies	B-100	619672	7/97	20 Ci
4	Shield Source Inc.	SLX-60	13-12844	4413	0.281 TBq
5	Shield Source Inc.	SLX-60	13-12840	4413	0.281 TBq
6	Shield Source Inc.	SLX-60	13-12841	4413	0.281 TBq
7	Isolite	2040	249583	1/04	7.5 Ci
8					
9					
10					

JF
Initial

10/09/20
Date

Please email this log to sales@tritiumdisposal.com or fax to: 614-863-0622.
Make sure to include your contact info if you have not already been assigned a TritiumDisposal account rep.



This Serial Number Log must also accompany each box as a packing slip and so must accurately reflect the inventory of EACH box.

Inventory Box Number: 4 of 4

Line	Manufacturer Name	Model Number	Serial Number	Date of Manufacture	Activity (Ci or TBq amount)
1	Isolite (BROKEN)	2000	231026	7/03	7.5 Ci
2	SRB Technologies (BROKEN)	B-100	649474	10/99	20 Ci
3					
4					
5					
6					
7					
8					
9					
10					

JF
Initial

10/9/2020
Date

Please email this log to sales@tritiumdisposal.com or fax to: 614-863-0622.
Make sure to include your contact info if you have not already been assigned a TritiumDisposal account rep.