

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Department of the Army, Headquarters, U.S. Army Joint
Munitions Command Safety and Risk Management Directorate
2695 Rodman Av., Rock Island, IL 61299-6000
Location Inspected, Anniston Munitions Center, Anniston AL

REPORT NUMBER(S) 2022002

2. NRC/REGIONAL OFFICE

Region III
U. S. Nuclear Regulatory Commission
2443 Warrenville Road, Suite 210
Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

040-08767

4. LICENSE NUMBER(S)

SUC-1380

5. DATE(S) OF INSPECTION

February 8, 2022

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

_____ Non-cited violation(s) were discussed involving the following requirement(s):

- ☐ 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

| TITLE | PRINTED NAME | SIGNATURE | DATE |
|---------------------------|-------------------|---|------|
| LICENSEE'S REPRESENTATIVE | | | |
| NRC INSPECTOR | Luis Nieves Folch | Luis A. Nieves Folch <small>Digitally signed by Luis A. Nieves Folch Date: 2022.02.23 11:19:56 -06'00'</small> | |
| BRANCH CHIEF | Michael Kunowski | Michael A. Kunowski <small>Digitally signed by Michael A. Kunowski Date: 2022.02.23 12:18:55 -06'00'</small> | |



Materials Inspection Record

| | | | | | |
|---|--|--|---|---|---------------------------------------|
| 1. Licensee Name: Department of the Army, | | 2. Docket Number(s): 040-08767 | | 3. License Number(s) SUC-1380 | |
| 4. Report Number(s): 2022002 | | | 5. Date(s) of Inspection: February 8, 2022 | | |
| 6. Inspector(s): Luis Nieves | | 7. Program Code(s): 11300 | | 8. Priority: 5 | 9. Inspection Guidance Used: 87126 |
| 10. Licensee Contact Name(s): Gary Buckrop, ARSO Don Winningham, site RSO | | 11. Licensee E-mail Address: gary.w.buckrop.civ@army.mil lester.d.winningham.civ@army.mil | | 12. Licensee Telephone Number(s): 309-782-8423 256-770-5060 | |
| 13. Inspection Type: <input checked="" type="checkbox"/> Routine <input checked="" type="checkbox"/> Announced <input type="checkbox"/> Non-Routine <input checked="" type="checkbox"/> Unannounced | | 14. Locations Inspected: <input type="checkbox"/> Main Office <input checked="" type="checkbox"/> Field Office <input type="checkbox"/> Temporary Job Site <input type="checkbox"/> Remote | | 15. Next Inspection Date (MM/DD/YYYY): January 13, 2027 <input type="checkbox"/> Normal <input type="checkbox"/> Extended <input type="checkbox"/> Reduced <input checked="" type="checkbox"/> No change | |

16. Scope and Observations:

This was an announced, routine inspection of a field office for the US Army Joint Munitions Command authorized to possess, receive, store, and transfer military devices containing depleted uranium ammunition and components. At the Anniston Munitions Center the licensee only receives, stores and transfers the devices.

PERFORMANCE OBSERVATIONS

The inspection consisted of interviews with selected licensee personnel, a review of selected records, a tour of the facility, security of the material and inventory verification. The inspector had the staff demonstrate/discuss inventory, audits, training, shipping, security, postings and surveys. Through these demonstrations and discussions, the inspector found the licensee's staff to be knowledgeable of radiation protection principles and regulatory requirements. The inspector reviewed a selection of records: inventory, shipping, training, surveys and audits.

No violations of NRC radiation safety requirements were identified as a result of this inspection.

From: [Nieves Folch, Luis](#)
To: gary.w.buckrop.civ@army.mil
Cc: lester.d.winningham.civ@army.mil
Subject: Army Munitions DU 591 inspection report
Date: Friday, February 25, 2022 6:57:00 AM
Attachments: [Army DU Ammunition 592M.pdf](#)
[Army DU Ammunition 591M\(1MK\).pdf](#)

Dear Mr. Buckrop and Mr. Winningham

Attach is the clear 591 report for the inspection conducted on February 8, 2022. At this point there is no further actions on your part.

In accordance with Title 10 of the Code of Federal Regulations 2.390 of the NRC's "Rules of Practice," a copy of this message will be available electronically for public inspection in the NRC's Public Document Room or from the NRC's Agencywide Documents Access and Management System (ADAMS), accessible from the NRC's website at <http://www.nrc.gov/reading-rm/adams.html>. Please feel free to contact me if you have any questions regarding this correspondence.

Thank you,

**Luis Nieves
Health Physicist
U.S. Nuclear Regulatory Commission
Division of Nuclear Materials Safety
Office: (630) 829-9571
Fax: (630) 515-1259**