

(SITE DOC)	01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25		
	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50		
(CLEARED)	Y	N	U		LICENSED		CONSTRUCTED		AEC		NRC		ORRNL		Other												
(COMMENT 1)																											
(CATEGORY)	1 (S-66)    1a(OR)    1b(NO)    1c(Und)    2(S-65)    X    3a(OR)    3b(NO)    X																										
(ACTION)	None    Re-eval(ORM)    License(ORC)    Visit    Other																										
(COMMENT 3)	ITEM # //																										

## ANALYSIS FORM

DOC NO

~~40~~ NoneCategory 2bBy CPHDate FEB 15 1979

ACCES NO

Category

By

Date

Category

By

Date

DOCUMENTS FOUND IN FOLDER: (Check nos. on reverse side under (SITE DOC) which apply.)

No. Document(s)

- 01 Appl. for Lic.  
02 Copy of Lic.  
03 Lic. Amendment(s)  
04 Reporting ID Symbol(s):  
05 Correspondence:  
06 Material Transfer Forms:  
07 Material Lease Form(s):  
08 Nuclear Material Draft:  
09 Materials Data Input:  
10 Waste Disposal:  
11 On-Site Waste Burial:  
12 Off-Site Waste Burial:  
13 Form 741 or 742:  
14 ☒ Quantities on Site: ☐ <1 gm ☐ <1 kg ☐ <10 kg ☐ <100 kg ☐ <1000 kg ☒ >1000 kg of: Th  
15 License Nos. NOT terminated: AS OF:  
16 Compliance Inspect Rept:  
17 Inspect Findings:  
18 Status Certificate:  
19 Contract No:  
20 Environmental Impact:  
21 Radiation Safety Check Form:  
22 Site Shut Down:  
23 Material Status Report:  
24  
25

NOTES:

No. Check List

- 26 One or more licenses expired AFTER 1965 (Category 1):  
27 ALL licenses terminated BEFORE 1966 (Category 2):  
28 Company Name changed:  
29 Company went out of business:  
30 Site not under responsible control:  
31 License covered more than one facility (site):  
32 Intra-Company Transfers:  
33 Radioactive material properly disposed of:  
34 Radioactive material improperly disposed of:  
35 Loaned or leased material returned:  
36 On-Site disposal:  
37 Off-site disposal to licensed group:  
38 Material never received under license:  
39 Incomplete accounting of materials:  
40 Site probably contaminated:  
41 Radiation survey rept(s):  
42 Radiation levels:  
43 10CFR citations:  
44 Transferred to State Licensing as of:  
45 Leak Test:  
46 Addn. Crossrefs:  
47

NOTES: