

SUBJECT Cracked screw from set "H"

PROJECT _____

6/8/95

COMPUTED BY _____

DATE _____

CHECKED BY _____

DATE _____

M. Hardness check on set (B) include in Table.

~~Attach Westinghouse spec~~

Attach Westinghouse spec

~~Over long term~~ ~~Cyclically temp~~

Crack - from set "G"

~~Not to be~~

etch to reveal case depth - include figure

Table III

Case core

~~Not to be~~

fracture + silica appears higher than rivet screws.

bottom of 1st page - mention zinc found in crack from "G"

~~Plating~~ → surface coating

~~lapping could lead to fatigue~~

~~intergranular fatigue~~

Boke A, + G

1-5
17-19

J/3