

## Form TI-1 Case Resolution

Case Status	<input type="checkbox"/> Open	<input checked="" type="checkbox"/> Closed
RCODE: __1145__		
Region: __1__		
OLD - Complete Name, Address, Contact, Phone Number: Avitex Fabric, Inc. Valley Forge, PA		
NEW - Complete Name, Address, Contact, Phone Number: Avtex Fibers, Inc. Valley Forge, PA		
Agreement State Licensee? (Double Check)	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Moved to an Agreement State?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Describe Follow-up: (Telephone, Internet, Chamber of Commerce, Other) Avtex Fibers, Inc. was a division or subsidiary of FMC Corporation, then was spun off as an independent corporation. It was headquartered in Valley Forge, but had no production facilities there.		
Describe Communication with Registration Vendor: John Saliwicki, KayRay/Sensall , 847-768-5691 The vendor showed no distribution that matched the distribution in the file. Avtex, which is now bankrupt, had at least two facilities with gauges: their largest facility in Fort Royal, Virginia and a facility in Nitro, West Virginia.		
Vendor Follow-up Action:		
Final Action Taken:		
Cause of Bad Address/Lesson Learned: Corrections need to be made to the information in the generally licensed device database before the device can be tracked. At a minimum, we need the location at which the device was located, rather than the licensee's mailing address (in this case, an office building that had no manufacturing facilities).		

## Form TI-2: Device Information

RCODE: __ 1145 __								
ID	Model Number	Serial Number	Isotope	Activity (mCi)	Sold Date	Vendor	Status (A or N)	Comments
1	3600		<sup>137</sup> Cs <sup>137</sup> Cs	250	19734	IL-01010-02	N	
For additional GLD's received by the licensee identified during the inspection:								
ID	Model Number	Serial Number	Isotope	Activity	Sold Date	Vendor	How obtained	Comments

Status Codes:

A - Source accounted for

N - Source not accounted for

## Form TI-3: General Licensee Inspection Documentation

RCODE: __1145__	
General Licensee Information:	
<input type="checkbox"/>	Check Box if Current Complete Name, Mailing Address, Contact, and Phone Number is Same as Provided by ORNL. If not, include correct information below:
<input type="checkbox"/>	
Results of inspection: (check the appropriate boxes)	
<input type="checkbox"/>	The general licensee of record is located at the address of record and
<input type="checkbox"/>	all GLD are accounted for
<input type="checkbox"/>	<u>not</u> all GLD are accounted for
<input type="checkbox"/>	The general licensee of record is <u>not</u> located at the address of record, however GLD are being used under new ownership at the address of record and
<input type="checkbox"/>	all GLD are accounted for
<input type="checkbox"/>	<u>not</u> all GLD are accounted for
<input type="checkbox"/>	The general licensee of record is <u>not</u> located at the address of record, however they are using GLD at another location and
<input type="checkbox"/>	all GLD are accounted for
<input type="checkbox"/>	<u>not</u> all GLD are accounted for;
X	Neither the general licensee of record nor the facility operated by the general licensee are located at the address of record and the site has been abandoned or is being used for an alternate purpose.
<input type="checkbox"/>	Other: (explain)
Gauge Information:	
ID	For each gauge for which status is unaccounted for (see last column of Form TI-2), provide any conclusions about location of the gauge:
<input type="checkbox"/>	
<input type="checkbox"/>	

The information in the file is not sufficient to track the gauge. Further effort is not justified.

Inspector: Keith Brown, Health Physicist  
Nuclear Materials Safety Branch 2

Approved By: John D. Kinneman, Chief  
Nuclear Materials Safety Branch 2