

IP2 Telecon - Licensee (pre pub mts)

- ① drips out of tubes from hot & cold legs when filled to 1st VSP.
They think it was condensation.

R2C5 top of U-land.

- ② Crack is segmented 2"-3" long. Max opening is $3/8"$.
Segments about $3/4"$

- ③ Will use bobbin & t-pint for this area of this tube.

- ④ Opinion is PWSCC

- ⑤ R2C67 had similar indication plugged in SC-2/4 in '97.

- ⑥ Can't see R2C5 crack in 1997 data.

J/16