

INPT - L

6-3-97



SG 21 - 16 defects  
22 - 50  
23 - 23  
24 - 20

~~AXIAL~~ Axial sludge pile .35" axial

SG 22 - INSIDE

① TS crevice SA1 2900 psig NO leak

② SA1 2900 NO leak

C 22 Sludge pile ~~50~~ 80 psig NO leak

④ Roll Trans SA1 2900 psig NO leak

SG 24 - 2 TS crevices

Rey

100% HL all complete

Bill Bateman, my boss, asked me to give you  
this. Phone call handwritten.

SG 21 > CL inspection  
SG 24

John T. Ad

ITEM #

5

M/B

+ point probe - coil w/ pancake  
- Gimbel at TSP w/ ~~dent~~ heavy dents  
only

rotation -  
speed

Calibrate on axial notches on ASME code.

- ① Need eddy current data TC-6700 Optical disk
- ② Analyst Setup
- ③ Analyst ~~data~~ Guidelines
- ④ drawing of Calibration Standards
- ⑤ Summary sheet eddy current.
- ⑥ Acquisition Technique sheet
- ⑦ Analyst technique sheet
- Calibrator notches & holes
- Gimbel used