

March 20, 2001

ST Environmental Professionals, Inc.
114 Lutz Road
Boyertown, PA 19512

Theodore Smith
Mailstop T-7F27
Two White Flint North
11545 Rockville Pike
Rockville, MD 20852-2738

Subject: Revere, PA Site Pictures
STEP Project No. 97C9048

Dear Ted,


Please find enclosed three copies each of the following:

- Copy of the aerial photograph from April 8, 1970 of the warehouse/loading dock area. (Attachment A.9 of the Revere Radiological Assessment, Rev. 1, 2001)
- Color enlargements of the pictures from the 1993 remediation effort by Bullinger's Mills. (Attachment A.8 of the Revere Radiological Assessment, Rev. 1, 2001)

I have located additional pictures of previous remediation activities performed at the Revere site. They are being processed/copied and will be transmitted in the near future.

Please call if you have any questions.

Yours truly,



Steffan R. Helbig, P.G.
President


Enclosure

CC: Tim Knapp, Cabot

C/17

Attachment A.9

Aerial Photograph of Warehouse Area (April 8, 1970)



Attachment A.8

Bullinger's Mill, Inc. Report on 1993 Remediation Effort



