



PROGRESS PICTURE NO. 11 - FEBRUARY 22, 1967

VIEW OF PLANT AREA FROM CONSTRUCTION PARKING AREA LOOKING NORTHEAST

Erection of the permanent fence is in progress. The construction power substation is seen at left center. The construction office building for Westinghouse Electric Corporation is at right center.

EBASCO SERVICES INCORPORATED



PROGRESS PICTURE NO. 45 - SEPTEMBER 26, 1967

VIEW OF SWITCHYARD AREA FROM TOP OF UNIT NO. 1 BOILER LOOKING SOUTHWEST

Grading of the swl chyard **active.** constructi of the nformation center
in rogress at top right.

EBASCO SERVICES INCORPORATED



PROGRESS PICTURE NO. 46 - SEPTEMBER 26, 1967

INFORMATION CENTER LOOKING NORTHWEST

Building footings have been concreted and construction of the exterior brick walls is in progress.

ERASSCO SERVICES INCORPORATED



PROGRESS PICTURE NO. 85 - MARCH 25, 1968

INFORMATION CENTER LOOKING NORTH

Construction of the Information Center is complete. Area lighting has been installed and roads and parking areas have been paved.

BRASCO SERVICES INCORPORATED

