



Supplementals

Safety, Health & Environmental Department
Building 119
P.O. Box 1608
Boyertown, PA 19512-1608

FAX: (610) 369-8691

FAX COVER SHEET


TO: COMPANY: _____
ATTENTION: Randy Ryland
FAX #: 610-337-5269
FROM: T. Knapp
DATE: 6/13/03
TOTAL PAGES (including cover): 2

IMPORTANT MESSAGE:

Randy,
Here is the survey requested. My consultant
had my survey file. Sorry for the delay
— Tim K

Pre & Post New Fence Installation

Note: If these copies are not legible, please contact Diane Pryor at (610) 369-8285.



Dr. J. T. Pottstown, PA 19464 * (610) 327-9610 * Fax (610) 327-9615
Website: www.jtical.com E-mail: info@jtical.com

PERFORMED 8-29-02

COMMENTS

॥

18/10

9) 15

$$\begin{array}{r} 8 \overline{) 15} \end{array}$$

7) 28

672

25

70

$$\frac{V_2}{V_1} = \frac{1}{2}$$
$$\frac{22}{27}$$

LOCATION AND READINGS

BKG: 18 $\mu\text{R/hr}$

CALIB. DUE DATE: JAN 9, 2003

USED • Micro ANALYST

INSTRUMENT.

~~JVI CALIBRATION SERVICES~~

GRAPHIC SCALE

Site Boundary

SLAG
PILE

RAIL

TRAVEL

WOODEN RETAINING WALL
205

ENCLOS

CHINA

285

250

250 -

20

240.

20/1/20