


- Project Boundary
- Radiological Assessment Grid
- Verification Blocks
- Supplemental Standards
- Adjacent Project

- Backfill
- Depth of Contamination
 - 6 in.
 - 12 in.



U.S. DEPARTMENT OF ENERGY GRAND JUNCTION, COLORADO		Work Performed by S.M. Stoller Corporation Under DOE Contract No. DE-AC01-02GJ79491	
Plate 1 Verification Grid for Highway 191 Phase 1 Showing Depth of Assessed Contamination			
DATE PREPARED: June 8, 2007		FILENAME: X0220000	