

KAWECKI BERYLCO INDUSTRIES, INC. ⁴¹⁸⁶



P. O. Box 429, Hazleton, Pa. 18201
Telephone: 717 / 455-4913

November 22, 1978

Mr. Paul R. Guinn
Radioisotopes Licensing Branch
Division of Fuel Cycle and Material Safety
Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Mr. Guinn:

Reference Mail Control No. 95981

The following information is supplied as requested in your letter of October 12, 1978 (copy attached).

The specific location at which the byproduct material is used is Tuckerton Road, Muhlenberg Township, Berks County, Pennsylvania.

Relative to Item 14, the leaks tests are performed by Boulder Scientific at their facility. We return the portion of the Model 200 device containing the sealed source to Boulder Scientific for source exchanges. Since for analytical purpose, we only use a source for three months, we return the device prior to the six month swipe test interval requirement and thus Boulder Scientific takes responsibility of performing the required test.

In regard to source exchanges, we are not performing this activity. As mentioned above, we return the portion of the Model 200 device containing the sealed source to Boulder Scientific for the source exchanges. The word shield as used in Items E15, E16, E18 and E19 of our instructions for using the Model 200 analyzer actually means that portion of the instrument that contains the sealed source.

I hope that the above information is sufficient to support our renewal application.

Truly yours,

KAWECKI BERYLCO INDUSTRIES, INC.


Paul C. Kempchinsky
Radiation Safety Officer

COPIES SENT TO OFF. OF
INSPECTION AND ENFORCEMENT

PCK/yyy
Attachment