



August 8, 2011

Mr. Lowell Spackman, District I Supervisor
Land Quality Division
Wyoming Department of Environmental Quality
122 W. 25th Street
Cheyenne, WY 82002

CAMECO RESOURCES
Smith Ranch-Highland
Operation
Mail:
P.O. Box 1210
Glenrock, WY
82637 USA

Tel: (307) 358-6541
Fax: (307) 358-4533
www.cameco.com

Certified Mail: Return Receipt Requested: #7009 2820 0001 4046 2799

RE: Missed Mechanical Integrity Testing, Cameco Resources, Smith Ranch Uranium Project,
Permit to Mine No. 603

Dear Mr. Spackman:

Cameco Resources, Smith Ranch Uranium Project is herein providing the status of one well recently discovered missed during the five-year Mechanical Integrity Test (MIT) and subsequently tested.

Mine Unit	Well	Date Found	5 Yr. MIT Due Date	J top Depth (ft.)	Pass Date
C	CMP-020I	7/21/2011	5/6/2011	600.0	7/28/11

MIT results will be reported in the appropriate Quarterly Reports to WDEQ/LQD.

Please contact me at (307) 358-6541, Ext. 435 if you have questions.

Sincerely,

A handwritten signature in cursive script that reads "Larry Teahon".

Larry Teahon
Interim SHEQ Manager

cc: File HUP 4.3.3.1
Doug Mandeville, USNRC (2 copies)
ec: CR - Cheyenne