



X	Y	LABEL
-1.3784	3.1663	W1-1
-5.7651	10.7641	W1-2
-1.3784	18.3621	W1-3
-5.7651	25.9601	W1-4
-1.3784	33.5581	W1-5
-5.7651	41.1561	W1-6
-1.3784	48.7541	W1-7
-5.7651	56.3521	W1-8
-1.3784	63.9501	W1-9
-5.7651	71.5481	W1-10
-1.3784	79.1461	W1-11
-5.7651	86.7441	W1-12
-62.7922	94.3421	W1-13
-54.0188	94.3421	W1-14
-45.2454	94.3421	W1-15
-36.472	94.3421	W1-16
-27.6986	94.3421	W1-17
-18.9252	94.3421	W1-18
-10.1518	94.3421	W1-19
-1.3784	94.3421	W1-20
-69.2203	101.2881	W1-21
4.3054	-5.5897	W1-22



Legend

- + Sample Locations
- Columns
- Excavation
Depth is 4 feet below concrete
- Excavation
Depth is 8 feet below concrete
- Walls
- South Trench

Excavation 2 Area: 20.05 sq m
Walls 2 Area: 64.4 sq m
Total Area: 84.09 sq m

Excavation 3 Area: 24.65 sq m
Walls 3 Area: 17.72 sq m
Total Area: 42.37 sq m

UNC SURVEY UNITS AND SAMPLE LOCATIONS

Former GE Facility New Haven Connecticut

Date: July 2011

Project #: New Haven

File Name: Figure

Prepared By: K. Wheatley

Figure

CABRERA SERVICES
RADIOLOGICAL • ENVIRONMENTAL • REMEDIATION