

**Cameco Resources
Crow Butte Operation**



**86 Crow Butte Road
P.O. Box 169
Crawford, Nebraska 69339-0169**

**(308) 665-2215
(308) 665-2341 – FAX**

June 8, 2012

**CERTIFIED MAIL
RETURN RECEIPT REQUESTED**

Michael Linder, Director
Nebraska Department of
Environmental Quality
P. O. Box 98922
Lincoln, Nebraska 68509-8922

Dear Mr. Linder:

On June 4, 2012, during routine 5-year Mechanical Integrity Testing (MIT), well number P-4501 in Mine Unit 10, Wellhouse 50 failed the MIT criteria. Using isolation techniques, it was determined that the failure is the casing joint at the 320-foot level. Jenny Coughlin, Groundwater Geologist UIC/ME, at Nebraska Department of Environmental Quality (NDEQ), Lindsey Phillips of the NDEQ field office in Chadron, Nebraska, and Ron Burrows, NRC Project Manager were notified concerning this well on June 4, 2012 at 2:15 p.m. MDT.

The joint that failed is located near the base of the red clay marker bed, two feet above the top of the basal Chadron sands, and twenty five feet below the bottom of the appetite zone which places the leak within the exempted aquifer. This data was reviewed with Jenny Coughlin and she concurred that the likelihood for contamination was minimal.

The nearest Shallow Monitor (SM) well to P-4501 is SM10-5. I have enclosed the latest results from SM10-5 for your review.

On June 7, 2012, Crow Butte repaired P-4501 by installing a sleeve to cover the failed joint. The well was successfully re-MIT'd which ensured the repair was sufficient.

If you have any questions or concerns on this matter, please do not hesitate to call me.

Sincerely,

Jim Stokey
General Manager

**Cameco Resources
Crow Butte Operation**




Page Two


Enclosures

cc: Lindsey Phillips – NDEQ
Ron Burrows – NRC
CBO – File
ec: CR - Cheyenne


SM10-5




SM10-5



SM10-5



SM10-5





7010 0780 0000 1422 0987



UNITED STATES POSTAGE
PITNEY BOWES
\$ 006.40⁰
02 1P
0003818154 JUN 08 2012
MAILED FROM ZIP CODE 69339

**RETURN RECEIPT
REQUESTED**



CAMECO RESOURCES

Crow Butte Operation
86 Crow Butte Road
P.O. Box 169
Crawford, NE
69339 USA

Mr. Ron Burrows, Project Manager
Decommissioning and Uranium Recovery Licensing
Directorate
Division of Waste Management and Environmental
Protection
Office of Federal and State Materials and
Environmental Management Programs
Mailstop T8-F5
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001