

Table 1. Comparison of Matrix, Fracture and Conduit Porosity

| | Porosity (%) | | |
|---|--------------|-----------|------------------|
| Setting | Matrix | Fractures | Conduit/Channels |
| Mammoth Cave, Kentucky, USA ¹ | 2.4 | 0.02 | 0.003 |
| Nohoch Na Chich, Yucatan, Mexico ¹ | 17 | 0.1 | 0.5 |
| The Chalk, UK ¹ | 30 | 0.01 | 0.02 |
| Woodville Karst Plain, Florida, USA | 27 | 0.1 | 0.02 |

¹ Worthington et al., 2000