

**CAMECO RESOURCES
CROW BUTTE OPERATION**



86 Crow Butte Road
P.O. Box 169
Crawford, Nebraska 69339-0169

(308) 665-2215
(308) 665-2341 – FAX

April 12, 2013

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

Michael Linder, Director
Nebraska Department of Environmental Quality
P. O. Box 98922
Lincoln, Nebraska 68509-8922

Dear Mr. Linder:

On January 18, 2013, during routine 10-year Mechanical Integrity Testing (MIT), well number P-3357 in Mine Unit 8, Wellhouse 39 failed the MIT criteria. Using isolation techniques, it was determined that the failure was in the casing joint at the 20-foot level. Shar Sapp, of the NDEQ field office in Chadron and Ron Burrows, NRC Project Manager were notified concerning this well on January 18, 2013.

Following isolation of the problem, a 5 foot sleeve was set using a drilling rig. The top of the sleeve is located at 17.5 feet and extends to 22.5 feet.

The well was then re-integrity tested on April 5, 2013 to check the entire well interval from 453 feet to the surface. A copy of the successful MIT is enclosed.

If you have any questions or concerns on this matter, please do not hesitate to call me.

Sincerely,

Doug Pavlick
General Manager

Enclosure

cc: Lindsey Phillips – NDEQ
Ron Burrows – NRC
CBO – File
ec: CR - Cheyenne



Nebraska Department of Environmental Quality

Casing Integrity Test Report

Company: Crow Butte

Permit No: NE0122611

Project: Crow Butte

Well No: 3357

Casing Type: Certa-Lok

Diameter: 4.5 in.

Hole Depth: 520 ft.

Casing Depth: 509 ft.

Screened Interval 1 Top: 475 ft.

Screened Interval 2 Top: ft.

Screened Interval 1 Bottom: 497 ft.

Screened Interval 2 Bottom: ft.

Screened Interval 3 Top: ft.

Screened Interval 4 Top: ft.

Screened Interval 3 Bottom: ft.

Screened Interval 4 Bottom: ft.

Depth to K-Packer: 464 ft.

Depth to Test Packer(s) Top: Ground Level ft.

Bottom: 453 ft.

Comments:

Rig Workover for 5yr Retest / Sleeved 5'

Well Tag ID Number: 3357

Test Performed By: Daniel H.

Date: 4/5/13

Calibration Performed By: D.H.

Date: 4/5/13

Time	Elapsed Time (Min)	Pressure (PSIG)
10:10	0	125
10:15	5	124
10:20	10	122
10:25	15	120
10:30	20	117

CERTIFICATION

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this application and all attachments and that, based on inquiry of those individuals immediately responsible for obtaining information, I believe that the information is true, accurate, and complete. Further, I certify awareness that there are significant penalties for submitting false information, including the possibility of a fine and imprisonment.

By Steven Boeselager

PRINTED NAME OF PERSON SIGNING

By

Steven Boeselager
SIGNATURE

Restoration Supervisor

TITLE

4-8-13

DATE



7010 0780 0000 1422 4619



UNIT
PITNEY BOWES
02 1P
\$ 006.77⁰
0003818154 APR 15 2013
MAILED FROM ZIP CODE 69339



CAMECO RESOURCES

Crow Butte Operation
86 Crow Butte Road
P.O. Box 169
Crawford, NE
69339 USA

Mr. Ron Burrows, Project Manager
Decommissioning and Uranium Recovery Licensing
Directorate
Division of Waste Management and Environmental
Protection
Office of Federal and State Materials and
Environmental Management Programs
Mailstop T8-F5
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

FWD
20852