

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9107230154 DOC. DATE: 91/07/11 NOTARIZED: NO DOCKET #
 FACIL: 50-361 San Onofre Nuclear Station, Unit 2, Southern California 05000361
 AUTH. NAME AUTHOR AFFILIATION
 NANDY, F.R. Southern California Edison Co.
 RECIPIENT NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: NPDES noncompliance notification: on 910511 total residual chlorine concentration combined discharge grab sample exceeded instantaneous limit. Evaluation in process. Corrective actions based upon evaluation findings.

DISTRIBUTION CODE: C001D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: Licensing Submittal: Environmental Rept Amdt & Related Correspondence

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD5 LA	3 3	PD5 PD	1 1
	KOKAJKO, L.	1 1		
INTERNAL:	ACRS	6 6	AEOD/DSP/TPAB	1 1
	NRR/DET/ESGB 8D	1 1	OC/LFMB	1 0
	OGC/HDS3	1 0	REG FILE <u>01</u>	1 1
	RGN5 DRSS/RPB	1 1		
EXTERNAL:	EG&G SIMPSON, F	2 2	NRC PDR	1 1
	NSIC	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 21 ENCL ~~19~~ 0



Southern California Edison Company

23 PARKER STREET
IRVINE, CALIFORNIA 92718

F. R. NANDY
MANAGER, NUCLEAR LICENSING

July 11, 1991

TELEPHONE
(714) 454-4504

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555

Gentlemen:

Subject: Docket No. 50-361
Report of NPDES Permit Violation, May 1991
San Onofre Nuclear Generating Station, Unit 2

Reference: June 28, 1991, letter from H. W. Newton (SCE) to A. L. Coe (California Regional Water Quality Control Board, San Diego Region), Subject: NPDES Monitoring Report, San Onofre Nuclear Generating Station, Unit 2

Section 3.2 of Appendix B to Facility License No. NPF-10 for San Onofre Nuclear Generating Station, Unit 2, requires Southern California Edison (SCE) to report violations of the National Pollutant Discharge Elimination System (NPDES) permit. This letter reports one NPDES permit violation at Unit 2. The referenced letter is provided as an enclosure.

There are nine sampling locations for different parameters required by the Unit 2 NPDES permit. The total residual chlorine concentration is determined at one of the nine sampling locations. The referenced letter indicated that on May 11, during normal operations, the total residual chlorine concentration in the Unit 2 combined discharge grab sample exceeded the NPDES permit INSTANTANEOUS limit by 20 $\mu\text{g/l}$. The NPDES permit DAILY limit for Total Residual Chlorine concentration is 200 $\mu\text{g/l}$. On May 13, the Combined Discharge total residual chlorine concentration was sampled and found to be below the NPDES permit INSTANTANEOUS limit. All remaining NPDES permit parameters during May 1991, were found to be within the specified limits.

9107230154 910711
PDR ADOCK 05000361
S PDR

COPI 1/0

July 11, 1991

An evaluation of this violation is currently in process. Corrective actions to prevent future violations, will be based upon the findings of this investigation.

There were no Unit 1 or Unit 3 NPDES permit violations in May 1991. If you require any additional information on this subject, please let me know.

Very truly yours,

A handwritten signature in black ink, appearing to be "J. B. Martin", written in a cursive style.

Enclosure

cc: J. B. Martin, Regional Administrator, NRC Region V
C. W. Caldwell, NRC Senior Resident Inspector, Units 1, 2 and 3