

## SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

## 1. LICENSEE/LOCATION INSPECTED:

Mistras Group, Inc.  
2410 Azurite Court, Suite B  
Anchorage, Alaska 99507

## 2. NRC/REGIONAL OFFICE

Region III  
U. S. Nuclear Regulatory Commission  
2443 Warrenville Road, Suite 210  
Lisle, IL 60532-4352

REPORT NUMBER(S) 2014-002

## 3. DOCKET NUMBER(S)

030-35114

## 4. LICENSE NUMBER(S)

12-16559-02

## 5. DATE(S) OF INSPECTION

April 9-17, 2014

## LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s):

- ☐ 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.  
(Violations and Corrective Actions)

## Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Don Stearns	<i>Don Stearns</i>	5/2/14
BRANCH CHIEF	Aaron T. McCraw	<i>Aaron T. McCraw</i>	5/2/14

*Docket File Information***SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

## 1. LICENSEE/LOCATION INSPECTED:

Mistras Group, Inc.  
2410 Azurite Court, Suite B  
Anchorage, Alaska 99507

REPORT NUMBER(S) 2014-002

## 2. NRC/REGIONAL OFFICE

Region III  
U. S. Nuclear Regulatory Commission  
2443 Warrenton Road, Suite 210  
Lisle, IL 60532-4352

## 3. DOCKET NUMBER(S)

030-35114

## 4. LICENSE NUMBER(S)

12-16559-02

## 5. DATE(S) OF INSPECTION

April 9-17, 2014

## 6. INSPECTION PROCEDURES USED

87121, 87137

## 7. INSPECTION FOCUS AREAS

All

**SUPPLEMENTAL INSPECTION INFORMATION**

## 1. PROGRAM CODE(S)

03320

## 2. PRIORITY

1

## 3. LICENSEE CONTACT

Nelson Perrin, General Manager Alaska

## 4. TELEPHONE NUMBER

(907) 522-2112

☐ Main Office Inspection

Next Inspection Date: \_\_\_\_\_

☒ Field Office Inspection 2410 Azurite Court, Suite B, Anchorage, AK☐ Temporary Job Site Inspection \_\_\_\_\_**PROGRAM SCOPE**

This was a routine field inspection of an industrial radiography company field office in Anchorage, Alaska. The primary focus was safety and compliance, and incorporation of the new Title 10 Code of Federal Regulations (CFR) 37 requirements.

**PERFORMANCE OBSERVATIONS**

The inspector toured the facility. Training records for the crews assigned to the two Alaska locations were checked. DOT Hazmat training and refresher training were up to date. Field audits were checked and found to be completed on a periodic basis. Leak check and inventory records were reviewed and found to be performed as required. The inspector reviewed all applicable safety requirements of industrial radiography.

No violations of NRC requirements were identified as a result of this inspection.