

APPENDIX B2.2

DRILLING PHOTOGRAPHS



NECR2-CC02 0-5'
10/29/13



NECR2-CC02 5-10'
10/29/13




NECR2-CC03 0-5'
10/29/13



NECR2-CC03 5-10'
10/29/13



NECR2-CC03 10-15'
10/29/13



NECR2-CC03 15-20'
10/29/13

Mine Site Drilling Photos
Northeast Church Rock Mine Site



NECR2-CC04 0-5'
10/29/13



NECR2-CC04 5-10'
10/29/13



NECR2-CC05 0-2.5'
10/29/13



NECR2-CC05 2.5-5'
10/29/13



NECR2-CC05 5-10'
10/29/13



NECR2-CC05 5-10'
10/29/13



NECR2-CC06 0-2.5'
10/30/13



NECR2-CC06 3.5-4'
10/30/13



NECR2-CC07 0-5'
10/30/13



NECR2-CC07 6.5-10'
10/30/13



Sand Fill 2 CC01 0-5'
10/29/13



Sand Fill 2 CC01 5-10'
10/29/13



Sand Fill 3 CC01 0-5'
10/30/13



Sand Fill 3 CC01 5-10'
10/30/13



Road-CC01
10/30/13



Road-CC01 5-10'
10/30/13



Road-CC02 0-5'
10/30/13



Road-CC02 5-10'
10/30/13



Road-CC03 0-5'
10/30/13



Road-CC03 5-10'
10/30/13



NECR1-CC01 15-20'
10/30/13



NECR1-CC02 0-5'
10/31/13



NECR1-CC03 0-5'
10/31/13



NECR1-CC04 0-5'
10/31/13