



GE Energy  
Inspection Services

August 18, 2014

U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D.C. 20555-0001

5425 Business Parkway  
Theodore, AL 36582  
US

T 251 653 6060  
F 251 653 0234

RE: Reply to a Notice of Violation Docket No. 030-38303  
Routine Inspection Report No. 03038303/2014001 (DNMS)

Please accept the responses below to the above-referenced Notice of Violations.

**NOV:** Title 10 of the Code of Federal Regulations (CFR) Part 34.20(b)(1)(v) requires licensees to ensure that each radiographic exposure device has attached to it a durable, legible, clearly visible label bearing the licensee's name, address, and telephone number.

Contrary to the above, as of June 11, 2014, the licensee failed to ensure that a radiographic exposure device at its Mt. Vernon, Indiana facility had attached to it a durable, legible, clearly visible label bearing the licensee's name, address and telephone number. Specifically, while the camera did have a label bearing the licensee's address or phone number.

**Response:** Full compliance was achieved on June 12, 2014, GE Inspection Services attached durable, legible, clearly visible labels with its name, address and telephone number on each radiographic exposure device.

Thank you for your consideration in this matter,  
Very Respectfully,

Neal Bishop  
Senior Operations Manager  
GE Inspection Services  
1211 Kona Drive  
Rancho Dominguez, CA 90220

Kirk W. Gros, CSP  
Corporate RSO  
EHS Leader-Southern Region & Inspection Services  
5425 Business Pkwy  
Theodore, AL 36582

IE07

cc:  
Ms. Cynthia Pederson  
Regional Administrator

U.S. NRC Region 3  
2443 Warrenville Road  
Suite 210  
Lisle, IL 60532

And

Mr. Aaron T. McCraw, Chief  
Materials Inspection Branch  
Division of Nuclear Materials Safety

U.S. NRC Region 3  
2443 Warrenville Road  
Suite 210  
Lisle, IL 60532