

Legend

- CLI Wells E-Wellfield
- Failed MIT Wells No Sand Impacted
- Wellfield Patterns


Monitor Ring




Permit 603

Permit 633

Reynolds

Sections



REVISIONS			 Camco Resources 762 Ross Road Douglas, WY 82633 Telephone: (307) 358-6541	E Wellfield T36N R73W No Sand Interval Plate 3H	 N 1" = 500'
SNO.	DATE	BY			
x 3/12/2015			xxxxxx		
Drawn by:  Y-Mike Beahere(SR)CCLL Report 2015/Naples Wellfield Plate 3H - 2015.mxd			SECTION NUMBER: Sheet - T36N R73W Plate 3H P3H-2B1 PROJECT NAME: Y-Mike Beahere(SR)CCLL Report 2015/Naples Wellfield Plate 3H - 2015.mxd		